


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Fabio Fernandes

GRE/Prodemge: João Antinossi Responsável/cliente: Robson de Oliveira

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SAUI-223882MbpsVSAT



Satellite (DVB) RX Configuration
----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176093 GHz Symbol Rate : 4.883010 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 17.1 dB
Input Power : -29 dBm

# dvb tx show

```
Satellite (DVB) TX Configuration
Auto start : Enabled IDU Output Power : -25 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -20.9 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Es/No
                     : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -357 us (281109 us)
Frequency correction: 20 Hz
# device show
System Information:
    Name
                         : SEE-SAUI-22388
    Location
                         : SANTA MARIA DO SUAÇUÍ - MG
    Contact
    System Up time : 0 days, 00:12:35 CPU Load : 20%
    System time(UTC) : 27 October 2017 11:43:18 Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
                         : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:52:46
Satellite (DVB) : 00:20:0e:10:52:46
# arp show
   NetAddr
                 State MacAddr
     10.215.4.2 Dynamic 00:23:5a:6b:ac:b8 1
Pinging 10.215.4.1 with 32 bytes of data:
Reply from 10.215.4.1: bytes=32 time=533ms TTL=56
Reply from 10.215.4.1: bytes=32 time=530ms TTL=56
Reply from 10.215.4.1: bytes=32 time=563ms TTL=56
Reply from 10.215.4.1: bytes=32 time=558ms TTL=56
Reply from 10.215.4.1: bytes=32 time=552ms TTL=56
Reply from 10.215.4.1: bytes=32 time=706ms TTL=56
Reply from 10.215.4.1: bytes=32 time=537ms TTL=56
Reply from 10.215.4.1: bytes=32 time=534ms TTL=56
Reply from 10.215.4.1: bytes=32 time=578ms TTL=56
Reply from 10.215.4.1: bytes=32 time=522ms TTL=56
Ping statistics for 10.215.4.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 706ms, Average = 561ms
```

## Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação:

Nome: Robson de Oliveira

Função: Diretor Masp: 338997-0

Telefone: 33-3431-5001

Funcionamento: 07:00 às 21:45h