


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Antonia Darc de Souza Lima

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet **VSAT** SEE-CORO-22012 2Mbps



PRINCIPAL DIAMENTAL DOOR - HOUSE GASSI

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

## Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State

DVB State

: On: Forward link up: 65281, Prodemge@Vodanet Network

: 12.176163 GHz : 4.883022 Msps Frequency Symbol Rate S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.3 dB SNR Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State : On (DVB-RCS2)
IDU Output Power : -21.3 dBm
ODU Output Power : 32.5 dBm
EIRP
                   : 45.8 dBW
                    : 14.5 dB
Es/No
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction
                    : -349 us (281672 us)
Frequency correction: 100 Hz
System Information:
    Name
                        : SEE-CORO-22012
    Location
                        : Conceição do Mato dentro
    Contact.
    System Up time : 0 days, 00:20:38
    CPU Load
                        : 6%
    System time(UTC) : 11 October 2017 15:39:29 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:57:e2
Satellite (DVB) : 00:20:0e:10:57:e2
arp show
   NetAddr
                State MacAddr
                                             Τf
    10.212.84.2 Dynamic 00:11:09:0c:63:84
Pinging 10.212.84.1 with 32 bytes of data:
Reply from 10.212.84.1: bytes=32 time=552ms TTL=56
Reply from 10.212.84.1: bytes=32 time=556ms TTL=56
Reply from 10.212.84.1: bytes=32 time=541ms TTL=56
Reply from 10.212.84.1: bytes=32 time=538ms TTL=56
Reply from 10.212.84.1: bytes=32 time=563ms TTL=56
Reply from 10.212.84.1: bytes=32 time=567ms TTL=56
Reply from 10.212.84.1: bytes=32 time=591ms TTL=56
Reply from 10.212.84.1: bytes=32 time=852ms TTL=56
Reply from 10.212.84.1: bytes=32 time=572ms TTL=56
Reply from 10.212.84.1: bytes=32 time=578ms TTL=56
Ping statistics for 10.212.84.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 538ms, Maximum = 852ms, Average = 591ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Antonia Darc de Souza Lima Função: Diretora
MASP: 321925-0
Telefone: (31) 97176-5540
Horário de funcionamento da escola: 08:00 as 17:00