


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Santos Operadora/Cliente: Gilvan P de Brito Júnior

GRE/Prodemge: João Antinossi Responsável/cliente: DINORA COSTA MORAES

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet 2048/1024 SEE-INIM-23233 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 12/12/2017 15:21:18

# dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E \* 0 0 8.883000

Yes

4.883300 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 03231, : 12.176453 GHz : 8.883180 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 22 16APSK-8/9

Pilot

```
Frame length
DVB S2 Mode
                    : Short
                    : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 15.6 dB
SNR
Input Power
                    : -37 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -15 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)
IDU Output Power : -14.8 dBm
Es/No : 13 0 '-
_____
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -328 us (266052 us)
Frequency correction: 110 Hz
# device show
System Information:
   Name
                        : SEE-INIM-23233
    Location
                        : Inhapim - MG
    Contact
                        :
   System Up time : 0 days, 00:58:29
CPU Load : 25%
System time(UTC) : 12 December 2017 14:46:39
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4b:1d
Satellite (DVB) : 00:20:0e:10:4b:1d
# arp show
  NetAddr State MacAddr
                                              Ιf
Pinging 10.215.215.1 with 32 bytes of data:
Reply from 10.215.215.1: bytes=32 time=522ms TTL=56
Reply from 10.215.215.1: bytes=32 time=547ms TTL=56
Reply from 10.215.215.1: bytes=32 time=600ms TTL=56
Reply from 10.215.215.1: bytes=32 time=518ms TTL=56
Reply from 10.215.215.1: bytes=32 time=583ms TTL=56
Reply from 10.215.215.1: bytes=32 time=519ms TTL=56
Reply from 10.215.215.1: bytes=32 time=578ms TTL=56
Reply from 10.215.215.1: bytes=32 time=588ms TTL=56
Reply from 10.215.215.1: bytes=32 time=558ms TTL=56
Reply from 10.215.215.1: bytes=32 time=636ms TTL=56
Ping statistics for 10.215.215.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
```

Minimum = 518ms, Maximum = 636ms, Average = 564ms
Lista de sites acessados:
<u>www.globo.com</u> – ok <u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok <u>www.educacao.mg.gov.br</u> – ok
www.prodemge.gov.br – ok
Nome do resp- DINORA COSTA MORAES
Tel - 33- 9 9900-1300 Cargo-DIRETORA
Masp- 379.154-8

