


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Claudinei Silva

GRE/Prodemge: João Antinossi Responsável/cliente: Gilmar Cruz Santos

Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet VSAT SEE-CULO-21916 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 9/10/2017 16:36:57

Satellite (DVB) RX Configuration ______

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

11.962753 DVB-S2 2 0 0.0 E 16.667000 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.175934 GHz : 4.882989 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 15.5 dB SNR : -31 dBm Input Power

```
Satellite (DVB) TX Configuration
 ______
Auto start
                                           : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                                           : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -14.4 dBm
ODU Output Power : 33.2 dBm
EIRP
                                            : 46.2 dBW
Es/No
                                            : 15.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -386 us (282090 us)
Frequency correction: 60 Hz
System Information:
        Name
                                                    : SEE-CULO-21916
         Location
                                                     : Curvelo
         Contact
        System Up time : 4 days, 22:52:41 CPU Load : 8%
        System time (UTC) : 09 October 2017 15:39:02
         Broadcast Message : not set
HW:
                                                    : SatLink 2000
        Model
         HW ID
                                                    : 120033
         Main board ID
                                                   : 120026 R6.2
        | : 00:20:0e:10:4c:2b 
MAC addresses:
        Ethernet (LAN)
Disparando 10.148.0.2 com 32 bytes de dados:
Resposta de 10.148.0.2: bytes=32 tempo=593ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=604ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=591ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=635ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=593ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=587ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=560ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=659ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=685ms TTL=57
Resposta de 10.148.0.2: bytes=32 tempo=613ms TTL=57
Estatísticas do Ping para 10.148.0.2:
        Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
                             perda),
Aproximar um número redondo de vezes em milissegundos:
         Mínimo = 560ms, Máximo = 685ms, Média = 612ms
```

Sites acessados
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Gilmar Cruz Santos Função: Vice-Diretor Identidade: Masp — 851.896-1

