


## **TERMO DE ACEITE TÉCNICO**

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Jefferson de Souza Marques Cliente: VIVO

EmpresaVSAT-IDLink kbpsPlataformaEMC BrasilVIVO-PER-23037458-CE256/128VSAT





```
_ 0 X
Telnet 10.29.9.177
Frequency correction: -290 Hz
Satellite (DVB) TX Configuration
Auto start : Enabled
IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : None
Satellite (DVB) Transmitter Status
State
IDU Output Power
ODU Output Power
                                On (TDMA)
-17.2 dBm
34.8 dBm
                                                                                                                       =
EIRP : 48.1 dBW
Eb/No : 14.5 dB
Header Compression : Disabled
Timing correction : -298 us (260544 us)
Frequency correction: -290 Hz
IP DVB 10.50.0.130/32
# ping 8.8.8.8
64 bytes from 8.8.8.8: time=1550 ms
64 bytes from 8.8.8.8: time=920 ms
64 bytes from 8.8.8.8: time=910 ms
64 bytes from 8.8.8.8: time=770 ms
64 bytes from 8.8.8.8: time=900 ms
--- 8.8.8.8 ping statistics ---
5 packets transmitted, 5 received,
                                                  0.00 percent packet loss
rtt min/avg/max = 770/1000/1550 ms
```