

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior


Operadora/Cliente Ederson Martins

Responsável/cliente Mariuza Machado

Consórcio
EMC/Vodanet

VSAT-ID
SEE-LAHA-23659
Porta kbps
2Mbps
VSAT





dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)

IDU Output Power : -18.2 dBm

Es/No : 16.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -313 us (266124 us)

Frequency correction: 110 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

```
Network
               : 65281, Prodemge@Vodanet
Frequency
               : 12.176426 GHz
                : 8.883128 Msps
Symbol Rate
S2 ModCod
   - receiving : 22 16APSK-8/9
   - current max : 22 16APSK-8/9
Pilot
            : On
Frame length
                : Short
DVB S2 Mode
                  : ACM
DVB S2 Stream type: MPEG-TS
Roll off
             : 0.20
             : 16.7 dB
SNR
Input Power
               : -35 dBm
# arp show
             State MacAddr
 NetAddr
                                  If
  10.215.18.2 Dynamic 1c:39:47:5b:e2:48 1
# device show
System Information:
                : SEE-LAHA-23659
  Name
  Location
                : Lajinha - MG
  Contact
  System Up time
                  : 0 days, 00:24:41
  CPU Load
                  : 23%
  System time(UTC) : 10 January 2018 15:49:20
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                 : 120033
  Main board ID
                   : 120026 R6.2
MAC addresses:
                   : 00:20:0e:10:7c:67
  Ethernet (LAN)
  Satellite (DVB)
                  : 00:20:0e:10:7c:67
Pinging 10.215.18.1 with 32 bytes of data:
Reply from 10.215.18.1: bytes=32 time=594ms TTL=56
Reply from 10.215.18.1: bytes=32 time=593ms TTL=56
Reply from 10.215.18.1: bytes=32 time=617ms TTL=56
Reply from 10.215.18.1: bytes=32 time=573ms TTL=56
Reply from 10.215.18.1: bytes=32 time=582ms TTL=56
Reply from 10.215.18.1: bytes=32 time=555ms TTL=56
Reply from 10.215.18.1: bytes=32 time=561ms TTL=56
Reply from 10.215.18.1: bytes=32 time=533ms TTL=56
Reply from 10.215.18.1: bytes=32 time=518ms TTL=56
Reply from 10.215.18.1: bytes=32 time=604ms TTL=56
Ping statistics for 10.215.18.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0\% loss),
Approximate round trip times in milli-seconds:
  Minimum = 518ms, Maximum = 617ms, Average = 573ms
Resp: Mariuza Machado
Masp: 1328309-8
Cargo: Secretaria
Tel:033-9-8461-2833
Horario:07:00-18:00
```

www.hotmail.com

www.google.com

Onde ficou: Na secretaria a pedido do diretor

 $\underline{www.prodemge.gov.br}$

www.globo.com

www.youtube.com