


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: José Ailton Coimbra Matos

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-MIAS-219302MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 10/10/2017 18:04:58

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176117 GHz Symbol Rate : 4.882775 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 14.7 dB
Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -16.6 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Es/No
                    : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -298 us (280907 us)
Frequency correction: 150 Hz
System Information:
                        : SEE-MIAS-21930
    Name
    Location
                        : MINAS NOVAS
    Contact
    System Up time : 0 days, 00:18:50 CPU Load : 21%
    System time (UTC) : 10 October 2017 17:14:49
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:48:a7
Satellite (DVB) : 00:20:0e:10:48:a7
    Ethernet (LAN)
Pinging 10.212.18.1 with 32 bytes of data:
Reply from 10.212.18.1: bytes=32 time=564ms TTL=56
Reply from 10.212.18.1: bytes=32 time=558ms TTL=56
Reply from 10.212.18.1: bytes=32 time=561ms TTL=56
Reply from 10.212.18.1: bytes=32 time=570ms TTL=56
Reply from 10.212.18.1: bytes=32 time=553ms TTL=56
Reply from 10.212.18.1: bytes=32 time=769ms TTL=56
Reply from 10.212.18.1: bytes=32 time=746ms TTL=56
Reply from 10.212.18.1: bytes=32 time=574ms TTL=56
Reply from 10.212.18.1: bytes=32 time=564ms TTL=56
Reply from 10.212.18.1: bytes=32 time=540ms TTL=56
Ping statistics for 10.212.18.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 540ms, Maximum = 769ms, Average = 599ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: José Ailton Coimbra Matos Função: Supervisor Identidade: MG 13155997