

TERMO DE ACEITE TÉCNICO


Responsável/cliente: JOÃO DE DEUS FERREIRA

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: EDERSON MARTINS PIRES

GRE/Prodemge: João Antinossi DOS ANJOS

Consórcio VSAT-ID Porta kbps **Plataforma** EMC/Vodanet SEE-SACO-22219 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 4/11/2017 13:17:06

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdoo

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176386 GHz Frequency Symbol Rate : 4.882972 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.4 dB Input Power : -30 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -17.9 dBm

ODU Output Power : 33.6 dBm

EIRP
_____
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -465 us (281786 us)
Frequency correction: 10 Hz
System Information:
   Name
                       : SEE-SACO-22219
    Location
                        : SO FRANCISCO
    Contact
    System Up time : 0 days, 00:39:58 CPU Load : 7%
    System time(UTC) : 04 November 2017 12:16:26
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
    Satellite (DVB) : 00:20:0e:10:51:c3
MAC addresses:
   Ethernet (LAN)
Pinging 10.213.18.1 with 32 bytes of data:
Reply from 10.213.18.1: bytes=32 time=562ms TTL=56
Reply from 10.213.18.1: bytes=32 time=540ms TTL=56
Reply from 10.213.18.1: bytes=32 time=890ms TTL=56
Reply from 10.213.18.1: bytes=32 time=545ms TTL=56
Reply from 10.213.18.1: bytes=32 time=593ms TTL=56
Reply from 10.213.18.1: bytes=32 time=545ms TTL=56
Reply from 10.213.18.1: bytes=32 time=573ms TTL=56
Reply from 10.213.18.1: bytes=32 time=615ms TTL=56
Reply from 10.213.18.1: bytes=32 time=550ms TTL=56
Reply from 10.213.18.1: bytes=32 time=552ms TTL=56
Ping statistics for 10.213.18.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 540ms, Maximum = 890ms, Average = 596ms
        State MacAddr
NetAddr
    10.213.18.3 Dynamic 48:ee:0c:c3:3e:39
```

Lista de sites acessados:

<u>www.globo.com</u> – ok

<u>www.yahoo.com</u> – ok

<u>www.hotmail.com</u> – ok

<u>www.google.com</u> – ok

www.educacao.mg.gov.br - ok

www.prodemge.gov.br – ok

Responsável pelo teste de navegação:

Nome: JOÃO DE DEUS FERREIRA DOS ANJOS

Função: Diretor

Telefone: 038-99835-7722

MASP: 815721-6

Horário de Funcionamento: 07 AS 17:30