


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

Responsável/cliente: Ângelo Márcio Andrade GRE/Prodemge: João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-COTO-21915 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 4/10/2017 14:35:55

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 * 0 0 4.883300 0 0.0 E

Yes

0 0.0 E 1 1 0.00000 0.000000 DVB-S2 0

No

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176425 GHz Frequency Symbol Rate : 4.883011 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.1 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : RTP/UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.3 dBm
ODU Output Power : 33.9 dBm
EIRP
                    : 47.2 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -1179 us (282018 us)
Frequency correction: 100 Hz
System Information:
    Name
                       : SEE-COTO-21915
    Location
                       : CORINTO - MG
    Contact
    System Up time : 0 days, 00:02:24 CPU Load : 9%
    System time(UTC) : 04 October 2017 13:41:59
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
    MAC addresses:
   Ethernet (LAN)
Disparando 10.148.0.13 com 32 bytes de dados:
Resposta de 10.148.0.13: bytes=32 tempo=622ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=603ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=585ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=567ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=587ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=600ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=563ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=554ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=564ms TTL=57
Resposta de 10.148.0.13: bytes=32 tempo=547ms TTL=57
Estatísticas do Ping para 10.148.0.13:
    Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
             perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 547ms, Máximo = 622ms, Média = 579ms
```

Lista de sites acessados:	
ununu alaha cama lak	
www.globo.com – ok	
www.hotmail.com – ok	
www.google.com – ok	
<u>www.educacao.mg.gov.br</u> – ok	
Responsável pelo teste de navegação: Nome: Ângelo Márcio Andrade Função: Vice-Diretor Identidade: MG 7284988	