


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Leandro Santos de Oliveira

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-COCI-23184 2Mbps



Satellite (DVB) RX Configuration ______

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prodei : 12.176316 GHz Frequency Symbol Rate : 4.882960 Msps

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.2 dB SNR : -31 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -15.4 dBm
ODU Output Power : 32.8 dBm
EIRP
                    : 46.1 dBW
Es/No
                    : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -391 us (281225 us)
Frequency correction: 20 Hz
System Information:
    Name
                       : SEE-COCI-23184
    Location
                        : Coroaci - MG
    Contact
    System Up time : 0 days, 00:44:20 CPU Load : 15%
    System time(UTC) : 04 December 2017 12:34:03
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4c:68
Satellite (DVB) : 00:20:0e:10:4c:68
    Ethernet (LAN)
NetAddr
             State MacAddr
   10.214.204.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.214.204.1 with 32 bytes of data:
Reply from 10.214.204.1: bytes=32 time=546ms TTL=56
Reply from 10.214.204.1: bytes=32 time=558ms TTL=56
Reply from 10.214.204.1: bytes=32 time=565ms TTL=56
Reply from 10.214.204.1: bytes=32 time=591ms TTL=56
Reply from 10.214.204.1: bytes=32 time=581ms TTL=56
Reply from 10.214.204.1: bytes=32 time=570ms TTL=56
Reply from 10.214.204.1: bytes=32 time=537ms TTL=56
Reply from 10.214.204.1: bytes=32 time=539ms TTL=56
Reply from 10.214.204.1: bytes=32 time=552ms TTL=56
Reply from 10.214.204.1: bytes=32 time=578ms TTL=56
Ping statistics for 10.214.204.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 537ms, Maximum = 591ms, Average = 561ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Leandro Santos de Oliveira Função: Professor MASP: 1309899-1 Telefone: 33-98831-3906 Funcionamento: 07:00h às 11:20h