

## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Jackson Alves Borges

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-CAAI-22923 2Mbps

> > Port eth0 on SEE-CAAI-22923 (10.215.103.1)





## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

## Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176477 GHz Frequency Symbol Rate : 4.883033 Msps

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.7 dB SNR : -36 dBm Input Power

```
Satellite (DVB) TX Configuration
______
                   : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)
IDU Output Power : -19.9 dBm
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -333 us (280542 us)
Frequency correction: 120 Hz
System Information:
   Name
                       : SEE-CAAI-22923
    Location
                        : Carai - MG
   Contact
   System Up time : 0 days, 00:16:56 CPU Load : 15%
   System time (UTC) : 24 November 2017 13:23:07
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
    HW ID
                       : 120033
                       : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5e:7f
Satellite (DVB) : 00:20:0e:10:5e:7f
NetAddr
             State MacAddr
  10.215.103.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.215.103.1 with 32 bytes of data:
Reply from 10.215.103.1: bytes=32 time=537ms TTL=56
Reply from 10.215.103.1: bytes=32 time=559ms TTL=56
Reply from 10.215.103.1: bytes=32 time=544ms TTL=56
Reply from 10.215.103.1: bytes=32 time=545ms TTL=56
Reply from 10.215.103.1: bytes=32 time=579ms TTL=56
Reply from 10.215.103.1: bytes=32 time=576ms TTL=56
Reply from 10.215.103.1: bytes=32 time=836ms TTL=56
Reply from 10.215.103.1: bytes=32 time=552ms TTL=56
Reply from 10.215.103.1: bytes=32 time=539ms TTL=56
Reply from 10.215.103.1: bytes=32 time=536ms TTL=56
Ping statistics for 10.215.103.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 536ms, Maximum = 836ms, Average = 580ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
<u>www.proderiige.gov.br</u> – Ok
Responsável pelo teste de navegação:
Nome: Jackson Alves Borges
Função: Vice-Diretor
MASP: 634146-5
Telefone: 33-35312118
Telefone. 33 33312110
Funcionamento: 07:00h às 17:30h