


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gustavo de Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente: Joilza Dias Coelho

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-SEHA-22974 2Mbps VSAT



## Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E \* 0 0 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

## Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176355 GHz Frequency Symbol Rate : 4.882932 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.5 dB Input Power : -30 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -21.0 dBm
ODU Output Power : 33.3 dBm
EIRP
                     : 46.6 dBW
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -370 us (280867 us)
Frequency correction: 40 Hz
System Information:
    Name
                        : SEE-SEHA-22974
    Location
                         : SETUBINHA
    Contact
    System Up time : 0 days, 00:22:02

CPU Load : 17%

System time(UTC) : 30 November 2017 12:54:02
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                         : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4c:a6
Satellite (DVB) : 00:20:0e:10:4c:a6
    Ethernet (LAN)
NetAddr
           State MacAddr
   10.215.173.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.215.173.1 with 32 bytes of data:
Reply from 10.215.173.1: bytes=32 time=545ms TTL=56
Reply from 10.215.173.1: bytes=32 time=525ms TTL=56
Reply from 10.215.173.1: bytes=32 time=533ms TTL=56
Reply from 10.215.173.1: bytes=32 time=538ms TTL=56
Reply from 10.215.173.1: bytes=32 time=548ms TTL=56
Reply from 10.215.173.1: bytes=32 time=543ms TTL=56
Reply from 10.215.173.1: bytes=32 time=536ms TTL=56
Reply from 10.215.173.1: bytes=32 time=610ms TTL=56
Reply from 10.215.173.1: bytes=32 time=537ms TTL=56
Reply from 10.215.173.1: bytes=32 time=583ms TTL=56
Ping statistics for 10.215.173.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 610ms, Average = 549ms
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Joilza Dias Coelho Função: Diretora MASP: 1163233-8 Telefone: 33-98822-3588 Funcionamento: 07:00h às 18:00h