


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Gildemar Vileiro dos Santos

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-MOIA-221922MbpsVSAT



Satellite (DVB) RX Configuration

Auto start : Enabled

May Traffic MODCOD : 23 16APSK-

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176300 GHz Symbol Rate : 4.882995 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 16.4 dB

Input Power : -29 dBm

```
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
                  : max
ODU Output Power
EIRP
                     : max
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -16.7 dBm
ODU Output Power : 34.7 dBm
EIRP
EIRP
                     : 48.0 dBW
Es/No
                     : 17.0 dB
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -385 us (281215 us)
Frequency correction: 130 Hz
# device show
System Information:
                         : SEE-MOIA-22192
    Name
    Location
                         : MONTALV NIA - MG
    Contact
    System Up time : 0 days, 00:39:22 CPU Load : 10%
    System time(UTC) : 28 October 2017 14:46:11 Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
                        : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4f:af Satellite (DVB) : 00:20:0e:10:4f:af
# arp show
   NetAddr
                State MacAddr
   10.212.245.2 Dynamic b4:99:ba:00:92:6b 1
#
C:\Documents and Settings\Administrator.DVB-RCS>ping -t 10.212.245.1
Pinging 10.212.245.1 with 32 bytes of data:
Reply from 10.212.245.1: bytes=32 time=584ms TTL=56
Reply from 10.212.245.1: bytes=32 time=577ms TTL=56
Reply from 10.212.245.1: bytes=32 time=548ms TTL=56
Reply from 10.212.245.1: bytes=32 time=584ms TTL=56
Reply from 10.212.245.1: bytes=32 time=541ms TTL=56
Reply from 10.212.245.1: bytes=32 time=564ms TTL=56
Reply from 10.212.245.1: bytes=32 time=522ms TTL=56
Reply from 10.212.245.1: bytes=32 time=542ms TTL=56
Reply from 10.212.245.1: bytes=32 time=575ms TTL=56
Reply from 10.212.245.1: bytes=32 time=565ms TTL=56
```

```
Ping statistics for 10.212.245.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 522ms, Maximum = 584ms, Average = 560ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação: Nome: Gildemar Vileiro dos Santos

Função: Vice Diretor Telefone: 38 99996-4610

MASP 1095694-4