


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Elvis Maicon Gonçalves Pereira

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-VAIA-22292 2Mbps



Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

Satellite (DVB) Receiver Status _____

Rx State : On DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65261, ... : 12.176257 GHz : 4.882880 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.4 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : RTP/UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.8 dBm
ODU Output Power : 33.4 dBm
EIRP
                     : 46.7 dBW
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -398 us (281277 us)
Frequency correction: 110 Hz
System Information:
              : SEE-VAIA-22292
    Name
    Location
                         : VARZELÂNDIA - MG
    Contact
    System Up time : 3 days, 21:27:51

CPU Load : 11%

System time(UTC) : 24 October 2017 11:38:09
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:63:7c
Satellite (DVB) : 00:20:0e:10:63:7c
NetAddr
             State MacAddr
    192.168.0.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.213.91.1 with 32 bytes of data:
Reply from 10.213.91.1: bytes=32 time=654ms TTL=56
Reply from 10.213.91.1: bytes=32 time=579ms TTL=56
Reply from 10.213.91.1: bytes=32 time=517ms TTL=56
Reply from 10.213.91.1: bytes=32 time=584ms TTL=56
Reply from 10.213.91.1: bytes=32 time=563ms TTL=56
Reply from 10.213.91.1: bytes=32 time=577ms TTL=56
Reply from 10.213.91.1: bytes=32 time=565ms TTL=56
Reply from 10.213.91.1: bytes=32 time=578ms TTL=56
Reply from 10.213.91.1: bytes=32 time=569ms TTL=56
Reply from 10.213.91.1: bytes=32 time=570ms TTL=56
Ping statistics for 10.213.91.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 517ms, Maximum = 654ms, Average = 575ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Elvis Maicon Gonçalves Pereira
Função: Vice-Diretor Identidade: MG 15.836.363
Telefone: 38-99945-8544
Horário de funcionamento – 07hrs às 22:30hrs