TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Guilherme Henrique	**Cliente:** VIVO

Empresa	VSAT-ID	Link kbps	Plataforma
EMC Brasil	VIVO-PER-31136417-MG	256k/128k	VSAT


```
# dvb tx show

Satellite (DVB) TX Configuration
-------------------------------
Auto start          : Enabled
IDU Output Power    : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power    : 33.7 dBm
EIRP                : 47.0 dBW
Default CW Frequency: 14.125750 GHz
ATM mode            : VC-Mux
Header Compression  :  None


Satellite (DVB) Transmitter Status
-------------------------------
State               : On  (DVB-RCS2)
```

```
IDU Output Power      : -16.9 dBm
ODU Output Power      : 33.6 dBm
EIRP                  : 46.9 dBW
Es/No                 : 12.5 dB
Header Compression    : Disabled
Timing correction     : -44 us (255475 us)
Frequency correction: 110 Hz
# dvb rx show


Satellite (DVB) RX Configuration
--------------------------------
Auto start            : Enabled
Max Traffic MODCOD     : 23   16APSK-9/10
RX watchdog           : 15 minute


Idx  Pri  SymbRate[Msps] Freq[GHz] Mode   PopId   SatId  Pos   SatName              Name
Enable
* 0  0    15.000000      12.059000 DVB-S2 102         0   0.0 E
Yes


Satellite (DVB) Receiver Status
--------------------------------
Rx State              : On
DVB State             : Forward link up
Network               : 1326,  T14R Beam
Frequency             : 12.059045 GHz
Symbol Rate           : 15.000188 Msps
S2 ModCod
      - receiving     : 7   QPSK-3/4
      - current max   : 18   16APSK-2/3
Pilot                 : On
Frame length          : Short
DVB S2 Mode           : ACM
DVB S2 Stream type    : MPEG-TS
Roll off              : 0.20
SNR                   : 12.1 dB
Input Power           : -32 dBm
```

SatLink VSAT × SpeedOf.Me, HTML5 Speed T... × +

10.29.38.105/wmi/dwp/index_page.dwp

Mais visitados Primeiros passos WhatsApp Galeria do Web Slice Sites Su... nts : Home

STM
SatLink VSAT

Status
Satellite
Statistics
Device
DHCP
Eventlog
Configuration
Satellite
IP
Static NAT
Lineup
Device
Help
Introduction
Status
Configuration

Device Status

Model	SatLink 2000
Software Version	16.0.1.57
LAN MAC Address	00:20:0e:10:60:95
DVB MAC Address	00:20:0e:10:60:95
System Up Time	0 days, 00:22:06
CPU Load	13%
System Name	VIVO-PER-31136417-MG
System Contact	
System Location	São João Del Rey- MG
ODU Serial Number	104804040203090404440000
ODU HW Version	4.2

You are logged in as insta...

© Copyright 2006-2014 STM Group. Al

```
Prompt de comando
Resposta de 8.8.8.8: bytes=32 tempo=583ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=562ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=542ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=852ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1206ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1454ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1300ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=792ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1085ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=530ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1299ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=522ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=538ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=508ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1179ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=932ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=761ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=624ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=535ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1908ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=516ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1074ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=616ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=528ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=511ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1152ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1440ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=929ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=636ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=589ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1146ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=2027ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=859ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=611ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=658ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=849ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=589ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=773ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1850ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=548ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=622ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=706ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1391ms TTL=55

Estatísticas do Ping para 8.8.8.8:
    Pacotes: Enviados = 188, Recebidos = 188, Perdidos = 0 (0% de perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 508ms, Máximo = 2531ms, Média = 1025ms
Control-C
^C
C:\Documents and Settings\Administrador>
```

quarta-feira, 24 de maio de 2017

Iniciar | SatLink VSAT - Mozilla Fir... | Prompt de comando | Skype | 11:46