


TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Leonardo Lourenço

GRE/Prodemge: João Antinossi Responsável/cliente: Warley Cardoso de Araújo

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet **VSAT** SEE-JOIA-23123 2Mbps





Satellite (DVB) RX Configuration ______

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.173500 DVB-S2 104 0 0.0 E * 0 0 13.333333

Yes

8.883000 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.173412 GHz : 13.332975 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.5 dB

```
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
IDU Output Power : -13.5 dBm
ODU Output Power : 33.8 dBm
EIRP
Es/No
                    : 16.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -162 us (258403 us)
Frequency correction: 120 Hz
System Information:
   Name
                        : SEE-JOIA-23123
    Location
                        : Jord nia - MG
    Contact
    System Up time : 0 days, 00:11:20 CPU Load : 34%
    System time(UTC) : 14 March 2018 19:18:46
Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:94:3a
Satellite (DVB) : 00:20:0e:10:94:3a
   Ethernet (LAN)
NetAddr
             State MacAddr
                                         Ιf
 10.214.38.2 Dynamic 00:40:a7:1d:fc:8d 1
Pinging 10.214.38.1 with 32 bytes of data:
Reply from 10.214.38.1: bytes=32 time=614ms TTL=56
Reply from 10.214.38.1: bytes=32 time=577ms TTL=56
Reply from 10.214.38.1: bytes=32 time=656ms TTL=56
Reply from 10.214.38.1: bytes=32 time=544ms TTL=56
Reply from 10.214.38.1: bytes=32 time=560ms TTL=56
Reply from 10.214.38.1: bytes=32 time=524ms TTL=56
Reply from 10.214.38.1: bytes=32 time=525ms TTL=56
Reply from 10.214.38.1: bytes=32 time=534ms TTL=56
Reply from 10.214.38.1: bytes=32 time=514ms TTL=56
Reply from 10.214.38.1: bytes=32 time=573ms TTL=56
Ping statistics for 10.214.38.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 514ms, Maximum = 656ms, Average = 562ms
```

www.globo.com – ok www.yahoo.com – ok www.hotmail.com – ok www.google.com – ok www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	
www.yahoo.com – ok www.hotmail.com – ok www.google.com – ok www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	Lista de sites acessados:
www.yahoo.com – ok www.hotmail.com – ok www.google.com – ok www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	www.globo.com . ok
www.hotmail.com – ok www.google.com – ok www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	
www.google.com – ok www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	
www.prodemge.gov.br – ok Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7	
Função: Secretário MASP: 1254370-7	www.prodemge.gov.br – ok
	Responsável: Warley Cardoso de Araújo Função: Secretário MASP: 1254370-7 Telefone: 33 3726-2096