```
Sem título
```

```
Reacquiring the Forward Link
Start Receiver tuning TS 9
Access Denied
Login: Receiver tuning failed for NIT TS (configured TS 9)
Password:
SatLink 2000
- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57
Reacquiring the Forward Link
Start Receiver tuning TS 9
Receiver tuning failed for NIT TS (configured TS 9)
Reacquiring the Forward Link
Start Receiver tuning TS 9
Receiver tuning failed for NIT TS (configured TS 9)
LOG SHOW at Up-Time 00 00:04:00
HW:
    Model
                          : SatLink 2000
                         : 120033
: 120026 R6. 2
    HW ID
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00: 20: 0e: 10: 7b: 6d
Satellite (DVB) : 00: 20: 0e: 10: 7b: 6d
SW versions:
    Boot : 14. 0. 1. 19
Current : 16. 0. 1. 57
Backup : 15. 0. 0. 34
Manual SW upgrade settings:
Server IP addr : 10.10.1.1
File name : new.tgz
Licenses for SW options:
    PEP-TCP
    Q0S-4
    RAC
    VLAN
    DVBS2-16APSK
     TRANSEC
System Information:
                         : TRE-MA-MOVEL_06
    Name
    Locati on
     Contact
    System Up time : 0 days, 00:03:51
System time(UTC) : not set, TDT not received
Broadcast Message : not set
Event log configuration:
    State : Log to file enabled
Severity logged : Major and higher
Max logfile size : 9 kB
All events logged to file
______
                                             Date Time Src Severity
Event
 2211 Tuning failure transponder one
```

	Sem títul			
Idx: 9 Srate: 15.000000 Frq: 12.059000 2212 Tuning failure transponder one	Md: DVB-S2	Up-lime	00 00: 15: 13	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2213 AUTOMATIC RESTART- NCR Lock til	Md: DVB-S2 meout	Up-Ti me Up-	00 00: 15: 17 Time 00 00: 15: 41	Maj or Cri t
ical 2214 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000 2215 Unit has restarted	Md: DVB-S2	Up-Time Up-	00 00: 15: 43 Ti me 00 00: 00: 09	Maj or Maj o
r				,
2216 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000 2217 Save Config Executed r	Md: DVB-S2		00 00:00:20 Time 00 00:01:38	Maj or Maj o
2218 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 01: 45	Maj or
2219 Tuning failure transponder one ldx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 02: 40	Maj or
2220 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 03: 00	Maj or
2221 Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 03: 07	Maj or
2222 Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 03: 30	Maj or
2223 Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 03: 37	Maj or
2224 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 03: 59	Maj or
2225 Tuning failure transponder one ldx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 04: 01	Maj or
2226 Tuning failure transponder one ldx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 04: 20	Maj or
2227 Tuning failure transponder one ldx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 04: 25	Maj or
2228 Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 04: 44	Maj or
2229 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 04: 48	Maj or
2230 Tuning failure transponder one ldx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00 00: 05: 11	Maj or
2231 Tuning failure transponder one ldx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 05: 18	Maj or
2232 Tuning failure transponder one ldx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 05: 38	Maj or
2233 Tuning failure transponder one ldx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00 00: 05: 42	Maj or
2234 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000 2235 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 05: 58	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2236 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 06: 00	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2237 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 06: 22	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2238 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 06: 27	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2239 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 06: 49	Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2240 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 06: 53	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2241 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 07: 13	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2242 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 07: 17	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000 2243 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00 00: 07: 37	Maj or

	C				
Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Sem títul Md:DVB-S2		00	00: 07: 38	Maj or
2244 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00	00: 07: 54	Maj or
2245 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00	00: 08: 02	Maj or
2246 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000		-			Maj or
2247 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000		-			Maj or
2248 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000		·			Maj or
2249 Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000		-			Maj or
2250 Tuning failure transponder one		-			_
Idx: 9 Srate: 15.000000 Frq: 12.059000 2251 Tuning failure transponder one		•			Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2252 Tuning failure transponder one		-			Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2253 Tuning failure transponder one		•			Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2254 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 09: 25	Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2255 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 09: 47	Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2256 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 09: 55	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00	00: 10: 11	Maj or
2257 Tuning failure transponder one ldx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00	00: 10: 15	Maj or
2258 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00	00: 10: 35	Maj or
2259 Tuning failure transponder one Idx: 9_Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00	00: 10: 39	Maj or
2260 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00	00: 10: 56	Maj or
2261 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000		-			Maj or
2262 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000		·			Maj or
2263 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000		•			Maj or
2264 Tuning failure transponder one		·			_
Idx: 9 Srate: 15.000000 Frq: 12.059000 2265 Tuning failure transponder one		•			Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2266 Tuning failure transponder one		-			Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2267 Tuning failure transponder one		•			Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2268 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 12: 20	Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2269 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 12: 40	Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2270 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 12: 41	Maj or
Idx: 9 Srate: 15.000000 Frq: 12.059000 2271 Tuning failure transponder one	Md: DVB-S2	Up-Ti me	00	00: 13: 04	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00	00: 13: 08	Maj or
2272 Tuning failure transponder one ldx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00	00: 13: 27	Maj or
2273 Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000	Md: DVB-S2	Up-Ti me	00	00: 13: 29	Maj or
2274 Tuning failure transponder one Idx: 9 Srate: 15.000000 Frq: 12.059000	Md: DVB-S2	Up-Ti me	00	00: 13: 48	Maj or
2275 Tuning failure transponder one	Dágina 3				•

	6			
ldx: 9 Srate: 15. 000000 Frq: 12. 05900			00 00: 13: 53	Maj or
2276 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900 2277 Tuning failure transponder or	00 Md: DVB-S2	Up-Ti me	00 00: 14: 12	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 05900 2278 Tuning failure transponder or	00 Md: DVB-S2	Up-Ti me	00 00: 14: 16	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 05900 2279 Tuning failure transponder or	00 Md: DVB-S2	Up-Ti me	00 00: 14: 36	Maj or
Idx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 14: 40	Maj or
2280 Tuning failure transponder or ldx: 9 Srate: 15.000000 Frq: 12.05900	00 Md: DVB-S2	Up-Ti me	00 00: 14: 57	Maj or
2281 Tuning failure transponder or ldx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 15: 01	Maj or
2282 Tuning failure transponder or ldx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 15: 23	Maj or
2283 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900 2284 AUTOMATIC RESTART- NCR Lock t	00 Md: DVB-S2		00 00:15:28 -Time 00 00:15:4	Major 41 Crit
ical 2285 Unit has restarted		Up	-Time 00 00:00:0	09 Majo
r 2286 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900 2287 Save Config Executed r	ne 00 Md:DVB-S2	Up-Time Up	00 00:00:21 -Time 00 00:01:3	Major 38 Majo
2288 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frg: 12.05900	00 Md: DVB-S2	Up-Time	00 00: 01: 43	Maj or
2289 Tuning failure transponder or ldx: 9 Srate: 15.000000 Frq: 12.05900	00 Md:DVB-S2	Up-Ti me	00 00: 02: 29	Maj or
2290 Tuning failure transponder or ldx: 9 Srate: 15.000000 Frq: 12.05900	00 Md: DVB-S2	Up-Ti me	00 00: 02: 48	Maj or
2291 Tuning failure transponder or ldx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 02: 55	Maj or
2292 Tuning failure transponder or ldx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 03: 12	Maj or
2293 Tuning failure transponder or ldx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 03: 13	Maj or
2294 Tuning failure transponder or Idx: 9 Srate: 15. 000000 Frq: 12. 05900	00 Md: DVB-S2	Up-Ti me	00 00: 03: 30	Maj or
2295 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900 2296 Unit has restarted after power	00 Md: DVB-S2		00 00:03:34 -Time 00 00:00:0	Major O9 Majo
2297 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frg: 12.05900	ne 00 Md:DVB-S2	Up-Time	00 00: 00: 20	Maj or
2298 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900	00 Md: DVB-S2	Up-Ti me	00 00: 01: 48	Maj or
2299 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900	00 Md:DVB-S2	Up-Time	00 00: 03: 28	Maj or
2300 Tuning failure transponder or Idx: 9 Srate: 15.000000 Frq: 12.05900	ne 00 Md:DVB-S2	Up-Ti me	00 00: 03: 50	Maj or
Frants stand in manage since Lost	. +	t		
Events stored in memory since last				
Event Unit has restarted after nower off		Date	lime Sro	c Severity
Tuning failure transponder one		op-11 lic	00 00.00.07	waj Oi
ime 00 00:00:20 Major Tuning failure transponder one			rq: 12. 059000 Md:	·
I dx:	9 Srate: 15. Pági na		rq: 12. 059000 Md:	DVB-S2 Up-T

Sem título ime 00 00:01:48 Maj or Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000 Md: DVB-S2 Up-T ime 00 00:03:28 Maj or Tuning failure transponder one Idx: 9 Srate: 15. 000000 Frq: 12. 059000 Md: DVB-S2 Up-T ime 00 00:03:50 Maj or Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9 Receiver tuning failed for NIT TS (configured TS 9) Reacquiring the Forward Link Start Receiver tuning TS 9

Receiver tuning failed for NIT TS (configured TS 9)