


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

Responsável/cliente: Rosane Ramos de Almeida GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet **VSAT** SEE-SACO-22234 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 24/10/2017 17:52:51

Satellite (DVB) RX Configuration \_\_\_\_\_

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 \* 0 0 4.883300 0 0.0 E

Yes

1 1 0 0.0 E 16.667000 11.962753 DVB-S2 2

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176286 GHz Frequency Symbol Rate : 4.882966 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On

Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 17.1 dB : -29 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -20.7 dBm
ODU Output Power : 33.0 dBm
EIRP
                    : 46.3 dBW
Es/No
                    : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -268 us (281631 us)
Frequency correction: 140 Hz
System Information:
    Name
                       : SEE-SACO-22234
    Location
                        : SÃO FRANCISCO - MG
    Contact
    System Up time : 0 days, 00:19:05
CPU Load : 21%
    System time (UTC) : 24 October 2017 16:30:25
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5c:8a
Satellite (DVB) : 00:20:0e:10:5c:8a
NetAddr
           State MacAddr
    10.213.33.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.33.1 with 32 bytes of data:
Reply from 10.213.33.1: bytes=32 time=529ms TTL=56
Reply from 10.213.33.1: bytes=32 time=557ms TTL=56
Reply from 10.213.33.1: bytes=32 time=600ms TTL=56
Reply from 10.213.33.1: bytes=32 time=562ms TTL=56
Reply from 10.213.33.1: bytes=32 time=671ms TTL=56
Reply from 10.213.33.1: bytes=32 time=566ms TTL=56
Reply from 10.213.33.1: bytes=32 time=568ms TTL=56
Reply from 10.213.33.1: bytes=32 time=577ms TTL=56
Reply from 10.213.33.1: bytes=32 time=596ms TTL=56
Reply from 10.213.33.1: bytes=32 time=574ms TTL=56
Ping statistics for 10.213.33.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 529ms, Maximum = 671ms, Average = 580ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
<u>www.google.com</u> – ok
<u>www.educacao.mg.gov.br</u> – ok <u>www.prodemge.gov.br</u> – ok
<u>www.proderrige.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: Rosane Ramos de Almeida
Função: Vice-Diretora Identidade: MASP 443.443-7
Telefone: 38-3631-6037
Horário de funcionamento – 07hrs às 17:15hrs