

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

GRE/Prodemge: João Antinossi

Consórcio
EMC/Vodanet


VSAT-ID
SEE-RIDO-22904

VSAT

Porta kbps
2Mbps

Plataforma
VSAT

Port eth0 SEE-RIDO-22904(10.214.45.1)



SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -18 dBm IDU Max Output Power: 0.0 dBm Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -17.8 dBm

Es/No : 11.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -326 us (280067 us)

Frequency correction: 100 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

```
Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName
Enable
* 0 0
                   12.176420 DVB-S2 104
                                             0.0E
       4.883300
                   11.962753 DVB-S2 2
                                            0 0.0 E
 1 1 16.667000
Satellite (DVB) Receiver Status
Rx State
              : On
DVB State
               : Forward link up
Network
               : 65281, Prodemge@Vodanet
Frequency
               : 12.176404 GHz
Symbol Rate
                : 4.883040 Msps
S2 ModCod
   - receiving : 21 16APSK-5/6
   - current max : 21 16APSK-5/6
Pilot
            : On
Frame length
                : Short
DVB S2 Mode
                  : ACM
DVB S2 Stream type : MPEG-TS
Roll off
             : 0.20
SNR
             : 15.0 dB
               : -45 dBm
Input Power
# arp show
             State MacAddr
 NetAddr
  10.214.45.2 Dynamic 64:1c:67:62:2e:12 1
# device show
System Information:
                : SEE-RIDO-22904
  Name
  Location
                : Rio Pardo de Minas - MG
  Contact
  System Up time
                    : 0 days, 00:26:46
  CPU Load
                  : 22%
  System time(UTC) : 29 November 2017 12:37:23
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                 : 120033
  Main board ID
                   : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:4f:4d
  Satellite (DVB)
                 : 00:20:0e:10:4f:4d
Pinging 10.214.45.1 with 32 bytes of data:
Reply from 10.214.45.1: bytes=32 time=533ms TTL=56
Reply from 10.214.45.1: bytes=32 time=586ms TTL=56
Reply from 10.214.45.1: bytes=32 time=577ms TTL=56
Reply from 10.214.45.1: bytes=32 time=564ms TTL=56
Reply from 10.214.45.1: bytes=32 time=517ms TTL=56
Reply from 10.214.45.1: bytes=32 time=736ms TTL=56
Reply from 10.214.45.1: bytes=32 time=539ms TTL=56
Reply from 10.214.45.1: bytes=32 time=617ms TTL=56
Reply from 10.214.45.1: bytes=32 time=530ms TTL=56
Reply from 10.214.45.1: bytes=32 time=542ms TTL=56
Ping statistics for 10.214.45.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0\% loss),
Approximate round trip times in milli-seconds:
  Minimum = 517ms, Maximum = 736ms, Average = 574ms
www.hotmail.com
```

Name

Yes

Yes

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com

Resp: Evander Martins Cargo: Diretor

Masp: 245876.5 Telefone: 033-3744-1194 Funcionamento: 07:00-22:30

Onde ficou: No rack instalado na secretária