


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Eleuza Pires de Vasconcelos

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-OUAS-228212MbpsVSAT



## Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

## Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176761 GHz Symbol Rate : 4.882995 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 16.0 dB

Input Power : -34 dBm

```
atellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.3 dBm
ODU Output Power : 33.8 dBm
EIRP
                    : 47.1 dBW
Es/No
                    : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -187 us (280659 us)
Frequency correction: 80 Hz
System Information:
    Name
                       : SEE-OUAS-22821
    Location
                        : Ouro Verde de Minas - MG
    Contact
    System Up time : 0 days, 00:13:44 CPU Load : 21%
    System time(UTC) : 14 November 2017 19:13:14
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4c:e6
Satellite (DVB) : 00:20:0e:10:4c:e6
    Ethernet (LAN)
NetAddr
            State MacAddr
   10.215.144.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.215.144.1 with 32 bytes of data:
Reply from 10.215.144.1: bytes=32 time=560ms TTL=56
Reply from 10.215.144.1: bytes=32 time=574ms TTL=56
Reply from 10.215.144.1: bytes=32 time=559ms TTL=56
Reply from 10.215.144.1: bytes=32 time=543ms TTL=56
Reply from 10.215.144.1: bytes=32 time=588ms TTL=56
Reply from 10.215.144.1: bytes=32 time=537ms TTL=56
Reply from 10.215.144.1: bytes=32 time=603ms TTL=56
Reply from 10.215.144.1: bytes=32 time=682ms TTL=56
Reply from 10.215.144.1: bytes=32 time=591ms TTL=56
Reply from 10.215.144.1: bytes=32 time=544ms TTL=56
Ping statistics for 10.215.144.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 537ms, Maximum = 682ms, Average = 578ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Eleuza Pires de Vasconcelos
Função: Diretora
MASP: 637896-2
Telefone: 38-988440420
Telefolie. 36-966440420
Funcionamento: 07:00 às 18:00h
Tuncionamento. 07.00 as 18.00n