

TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior


Operadora/Cliente Ronaldo Candido

Responsável/cliente Cleinton Martins

Consórcio
EMC/Vodanet

VSAT-ID
SEE-RIAS-22556
Porta kbps
2Mbps
Plataforma
VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176438 GHz Symbol Rate : 4.882977 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

```
DVB S2 Stream type: MPEG-TS
Roll off
            : 0.20
             : 16.9 dB
SNR
               : -35 dBm
Input Power
# dvb tx show
Satellite (DVB) TX Configuration
          : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
             : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
            : On (DVB-RCS2)
IDU Output Power : -18.8 dBm
ODU Output Power : 33.1 dBm
             : 46.4 dBW
Es/No
             : 12.0 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction : -324 us (280722 us)
Frequency correction: 120 Hz
# arp show
             State MacAddr
 NetAddr
  10.213.139.2 Dynamic 80:ee:73:a4:e2:ba 1
# device show
System Information:
                : SEE-RIAS-22556
  Name
  Location
                : RIO PARDO DE MINAS - MG
  Contact
  System Up time
                   : 0 days, 00:16:22
                  : 24%
  CPU Load
  System time(UTC) : 10 November 2017 16:57:07
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                : 120033
  Main board ID
                  : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:5c:b9
  Satellite (DVB)
                  : 00:20:0e:10:5c:b9
Pinging 10.213.139.1 with 32 bytes of data:
Reply from 10.213.139.1: bytes=32 time=592ms TTL=56
Reply from 10.213.139.1: bytes=32 time=552ms TTL=56
Reply from 10.213.139.1: bytes=32 time=543ms TTL=56
Reply from 10.213.139.1: bytes=32 time=533ms TTL=56
Reply from 10.213.139.1: bytes=32 time=530ms TTL=56
Reply from 10.213.139.1: bytes=32 time=559ms TTL=56
```

Reply from 10.213.139.1: bytes=32 time=561ms TTL=56 Reply from 10.213.139.1: bytes=32 time=570ms TTL=56 Reply from 10.213.139.1: bytes=32 time=561ms TTL=56 Reply from 10.213.139.1: bytes=32 time=524ms TTL=56

Ping statistics for 10.213.139.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds:

Minimum = 524ms, Maximum = 592ms, Average = 552ms

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Cleinton Martins
Cargo	Diretor
Identidade	1188315-4
Telefone	038-9-9139-1429//9-9929-1429
Funcionamento	06:00 às 11:30