


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Roosevelt Ferraz de Souza

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-RUIM-231282MbpsVSAT



Satellite (DVB) RX Configuration ----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Bandwidth Traffic IN Bandwidth Traffic OUT

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176236 GHz Symbol Rate : 4.882921 Msps

S2 ModCod

- receiving : 14 8PSK-3/4 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 16.0 dB

Input Power : -30 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -19.0 dBm

ODU Output Power : 34.6 dBm

EIRP
______
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -336 us (280009 us)
Frequency correction: -30 Hz
System Information:
    Name
                        : SEE-RUIM-23128
    Location
                         : Rubim - MG
    Contact
    System Up time : 0 days, 00:04:09 CPU Load : 15%
    System time (UTC) : 06 December 2017 12:15:14
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
    Eunernet (LAN) : 00:20:0e:10:64:34
Satellite (DVB) : 00:20:0e:10:64:34
MAC addresses:
NetAddr
           State MacAddr
    10.214.47.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.214.47.1 with 32 bytes of data:
Reply from 10.214.47.1: bytes=32 time=549ms TTL=56
Reply from 10.214.47.1: bytes=32 time=569ms TTL=56
Reply from 10.214.47.1: bytes=32 time=528ms TTL=56
Reply from 10.214.47.1: bytes=32 time=525ms TTL=56
Reply from 10.214.47.1: bytes=32 time=533ms TTL=56
Reply from 10.214.47.1: bytes=32 time=531ms TTL=56
Reply from 10.214.47.1: bytes=32 time=554ms TTL=56
Reply from 10.214.47.1: bytes=32 time=547ms TTL=56
Reply from 10.214.47.1: bytes=32 time=578ms TTL=56
Reply from 10.214.47.1: bytes=32 time=548ms TTL=56
Ping statistics for 10.214.47.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 578ms, Average = 546ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Roosevelt Ferraz de Souza Função: Diretor MASP: 813600-4 Telefone: 33-98864-6530 Funcionamento: 07:00h às 22:00h