


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Francisco Cezar Pereira

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-CATI-21932 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 18/10/2017 19:32:21

Satellite (DVB) RX Configuration

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 \* 0 0 4.883300 0 0.0 E

Yes

0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176215 GHz Symbol Rate : 4.883115 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off SNR : 15.5 dB Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.7 dBm
ODU Output Power : 32.9 dBm
EIRP
                     : 46.2 dBW
Es/No
                     : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -235 us (280764 us)
Frequency correction: 90 Hz
System Information:
                    : SEE-CATI-21932
    Name
    Location
                         : CATUTI
    Contact
    System Up time : 0 days, 00:16:37

CPU Load : 13%

System time(UTC) : 18 October 2017 18:36:53
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4a:f2
Satellite (DVB) : 00:20:0e:10:4a:f2
NetAddr
            State MacAddr
    10.212.20.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.212.20.1 with 32 bytes of data:
Reply from 10.212.20.1: bytes=32 time=570ms TTL=56
Reply from 10.212.20.1: bytes=32 time=535ms TTL=56
Reply from 10.212.20.1: bytes=32 time=560ms TTL=56
Reply from 10.212.20.1: bytes=32 time=551ms TTL=56
Reply from 10.212.20.1: bytes=32 time=546ms TTL=56
Reply from 10.212.20.1: bytes=32 time=573ms TTL=56
Reply from 10.212.20.1: bytes=32 time=572ms TTL=56
Reply from 10.212.20.1: bytes=32 time=563ms TTL=56
Reply from 10.212.20.1: bytes=32 time=562ms TTL=56
Reply from 10.212.20.1: bytes=32 time=565ms TTL=56
Ping statistics for 10.212.20.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 573ms, Average = 559ms
```

Lista de sites acessados:
www.globo.com – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – <b>ok</b>
<u>www.prodemge.gov.br</u> – <b>o</b> k
Responsável pelo teste de navegação:
Nome: Francisco Cezar Pereira
Função: ATB/Professor Identidade: MASP 1057216-2
Horário de funcionamento – 07hrs às 21hrs