

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gustavo de Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente: Alex-Sandra Reis Alves Furtado

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-BOHO-23367 2Mbps

#### Port eth0 on SEE-BOHO-23367 (10.214.121.1)



### Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E \* 0 0 8.883000

Yes

#### Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 03201, : 12.176363 GHz : 8.882915 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.4 dB Input Power : -40 dBm

```
Satellite (DVB) TX Configuration
_____
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -20.0 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -195 us (266290 us)
Frequency correction: 210 Hz
System Information:
   Name
                        : SEE-BOHO-23367
    Location
                        : Bom Jesus do Galho - MG
    Contact
    System Up time : 0 days, 00:08:17 CPU Load : 24%
                       : 11 December 2017 20:39:48
    System time(UTC)
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
                       : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:82
Satellite (DVB) : 00:20:0e:10:4c:82
NetAddr
          State MacAddr
   10.214.121.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.214.121.1 with 32 bytes of data:
Reply from 10.214.121.1: bytes=32 time=535ms TTL=56
Reply from 10.214.121.1: bytes=32 time=554ms TTL=56
Reply from 10.214.121.1: bytes=32 time=806ms TTL=56
Reply from 10.214.121.1: bytes=32 time=536ms TTL=56
Reply from 10.214.121.1: bytes=32 time=620ms TTL=56
Reply from 10.214.121.1: bytes=32 time=558ms TTL=56
Reply from 10.214.121.1: bytes=32 time=586ms TTL=56
Reply from 10.214.121.1: bytes=32 time=627ms TTL=56
Reply from 10.214.121.1: bytes=32 time=544ms TTL=56
Reply from 10.214.121.1: bytes=32 time=518ms TTL=56
Ping statistics for 10.214.121.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 518ms, Maximum = 806ms, Average = 588ms
```

# Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Alex-Sandra Reis Alves Furtado Função: Vice Diretora MASP: 915296-5 Telefone: 33-999194260 Funcionamento: 07:00h às 21:00h