


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Ederson Martins	
GRE/Prodemge: João Antinossi		Responsável/cliente Eric Mendes de Matos	
Consórcio EMC/Vodanet	VSAT-ID SEE-SACO-22214	Porta kbps 2Mbps	Plataforma VSAT





SatLink 2000

- Main board ID 120026, Revision R6.1
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176229 GHz Symbol Rate : 4.883012 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 14.8 dB Input Power : -36 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -20.0 dBm
ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW Es/No : 12.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -264 us (281580 us)

Frequency correction: 140 Hz

arp show

NetAddr State MacAddr If 10.213.13.2 Dynamic 1c:39:47:5b:e2:48 1

device show

System Information:

Name : SEE-SACO-22214

Location : SO FRANCISCO - MG

Contact :

System Up time : 0 days, 00:08:27

CPU Load : 13%

System time(UTC) : 31 October 2017 18:50:20

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.1

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:48:e0 Satellite (DVB) : 00:20:0e:10:48:e0

Pinging 10.213.13.1 with 32 bytes of data:

```
Reply from 10.213.13.1: bytes=32 time=536ms TTL=56 Reply from 10.213.13.1: bytes=32 time=546ms TTL=56 Reply from 10.213.13.1: bytes=32 time=528ms TTL=56 Reply from 10.213.13.1: bytes=32 time=559ms TTL=56 Reply from 10.213.13.1: bytes=32 time=555ms TTL=56 Reply from 10.213.13.1: bytes=32 time=584ms TTL=56 Reply from 10.213.13.1: bytes=32 time=566ms TTL=56 Reply from 10.213.13.1: bytes=32 time=579ms TTL=56 Reply from 10.213.13.1: bytes=32 time=563ms TTL=56 Reply from 10.213.13.1: bytes=32 time=567ms TTL=56 Reply from 10.213.13.1: bytes=32 time=567ms TTL=56
```

Ping statistics for 10.213.13.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 528ms, Maximum = 584ms, Average = 568ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Eric Mendes de Matos
Cargo	DIRETOR
Identidade	595.595.0
Telefone	038-9-9967-7612
Funcionamento	07:00 até 17:15