

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

Responsável/cliente: CLEIDE MADUREIRA FERREIRA GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-PAEM-23790 2Mbps **VSAT**





Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 * 0 0 12.176420 DVB-S2 104 0 0.0 E

Yes

0 0.0 E 4.883300 12.176420 DVB-S2 2 1 1

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet : 12.176408 GHz Network

Frequency : 8.882765 Msps Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot Frame length : Snor : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.4 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -17.9 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -205 us (266518 us)
Frequency correction: 160 Hz
System Information:
    Name
                        : SEE-PAEM-23790
    Location
                         : Passab m - MG
    Contact
    System Up time : 0 days, 00:08:03
CPU Load : 17%
System time(UTC) : 19 January 2018 20:13:33
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:93:fc
Satellite (DVB) : 00:20:0e:10:93:fc
NetAddr
           State MacAddr
    10.215.83.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.215.83.1 with 32 bytes of data:
Reply from 10.215.83.1: bytes=32 time=571ms TTL=56
Reply from 10.215.83.1: bytes=32 time=564ms TTL=56
Reply from 10.215.83.1: bytes=32 time=558ms TTL=56
Reply from 10.215.83.1: bytes=32 time=557ms TTL=56
Reply from 10.215.83.1: bytes=32 time=524ms TTL=56
Reply from 10.215.83.1: bytes=32 time=538ms TTL=56
Reply from 10.215.83.1: bytes=32 time=531ms TTL=56
Reply from 10.215.83.1: bytes=32 time=556ms TTL=56
Reply from 10.215.83.1: bytes=32 time=581ms TTL=56
Reply from 10.215.83.1: bytes=32 time=557ms TTL=56
Ping statistics for 10.215.83.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 524ms, Maximum = 581ms, Average = 553ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
<u>www.proderinge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: CLEIDE MADUREIRA FERREIRA
Função: SECRETARIA
MASP: 369636-6
Telefone: (31) 3836-1108
Horário: 07:00 as 17:00
1101a110. 07.00 as 17.00