


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Sandra Maria Barbosa

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-MIAS-220392MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 10/10/2017 14:25:26

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176352 GHz Symbol Rate : 4.883066 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 15.4 dB

Input Power : -33 dBm

```
Satellite (DVB) TX Configuration
-----
                    : Enabled
Auto start
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -12.8 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.1 dBW
Es/No
                     : 16.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -372 us (280896 us)
Frequency correction: 20 Hz
System Information:
    Name
                        : SEE-MIAS-22039
    Location
                         : MINAS NOVAS
    Contact
                        :
    System Up time : 0 days, 00:13:00

CPU Load : 12%

System time(UTC) : 10 October 2017 13:30:28
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
                     : 00:20:0e:10:4a:83
    Ethernet (LAN)
    Satellite (DVB)
                        : 00:20:0e:10:4a:83
Pinging 10.212.111.1 with 32 bytes of data:
Reply from 10.212.111.1: bytes=32 time=560ms TTL=56
Reply from 10.212.111.1: bytes=32 time=573ms TTL=56
Reply from 10.212.111.1: bytes=32 time=609ms TTL=56
Reply from 10.212.111.1: bytes=32 time=601ms TTL=56
Reply from 10.212.111.1: bytes=32 time=587ms TTL=56
Reply from 10.212.111.1: bytes=32 time=588ms TTL=56
Reply from 10.212.111.1: bytes=32 time=569ms TTL=56
Reply from 10.212.111.1: bytes=32 time=647ms TTL=56
Reply from 10.212.111.1: bytes=32 time=546ms TTL=56
Reply from 10.212.111.1: bytes=32 time=588ms TTL=56
Ping statistics for 10.212.111.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 546ms, Maximum = 647ms, Average = 586ms
```

Lista de sites acessados:
www.globo.com - ok
www.hotmail.com – ok
<u>www.google.com</u> – ok <u>www.educacao.mg.gov.br</u> – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: Sandra Maria Barbosa Função: Secretária Identidade: MG 545583287