

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Henrique Operadora/Cliente: Jean Polini

Responsável/cliente: Klepson Nark Moreira Dias GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma EMC/Vodanet** SEE-PAAO-22953 2Mbps **VSAT**

Port eth0 on SEE-PAAO-22953 (10.215.148.1)



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

13.333333 12.173500 DVB-S2 104 * 0 0 0 0.0 E

Yes

12.173500 DVB-S2 104 0 0.0 E 1 13.333333 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet : 12.173504 GHz Network

Frequency : 13.332788 Msps Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

: On Pilot Frame length : Short
DVB S2 Mode : ACM DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20

```
SNR
                    : 13.9 dB
Input Power
                   : -44 dBm
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                   : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.9 dBm
Es/No : 13.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -203 us (259042 us)
Frequency correction: 130 Hz
#
# device show
System Information:
                       : SEE-PAAO-22953
   Name
   Location
                       : PAV O- MG
   Contact
   System Up time : 2 days, 08:36:34 CPU Load : 32%
    System time(UTC) : 15 March 2018 19:04:39 Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5c:4f
Satellite (DVB) : 00:20:0e:10:5c:4f
#
#
#
# arp show
                State MacAddr
  10.215.148.26 Pending 00:00:00:00:00:00 1
Pinging 10.215.148.1 with 32 bytes of data:
Reply from 10.215.148.1: bytes=32 time=593ms TTL=56
Reply from 10.215.148.1: bytes=32 time=567ms TTL=56
Reply from 10.215.148.1: bytes=32 time=589ms TTL=56
Reply from 10.215.148.1: bytes=32 time=618ms TTL=56
Reply from 10.215.148.1: bytes=32 time=791ms TTL=56
Reply from 10.215.148.1: bytes=32 time=547ms TTL=56
Reply from 10.215.148.1: bytes=32 time=545ms TTL=56
Reply from 10.215.148.1: bytes=32 time=518ms TTL=56
```

```
Reply from 10.215.148.1: bytes=32 time=604ms TTL=56
Reply from 10.215.148.1: bytes=32 time=603ms TTL=56

Ping statistics for 10.215.148.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 518ms, Maximum = 791ms, Average = 597ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação: Nome: Klepson Nark Moreira Dias

Função: Diretor MASP: 816126-7