

TERMO DE ACEITE TÉCNICO

Solicitante: Vivo

NOC/Operador: Ermínio Junior.

EmpresaVSAT-IDLink kbpsPlataformaEMC BrasilVIVO-PER-31238856-MG256kb-128kbVSAT



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 9.320000 12.055825 DVB-S2 4 0 0.0 E

Yes

9 9 15.000000 12.059000 DVB-S2 4 0 0.0 E

```
Yes
Satellite (DVB) Receiver Status
-----
Rx State : On

DVB State : Forward link up

Network : 1326, T14R Beam

Frequency : 12.055878 GHz

Symbol Rate : 9.319902 Msps
S2 ModCod
     - receiving : 14 8PSK-3/4
      - current max : 16 8PSK-8/9
Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR
                      : 13.0 dB
Input Power
               : -31 dBm
Satellite (DVB) TX Configuration
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 32.8 dBm
EIRP
                     : 52.0 dBW
Default CW Frequency: 14.125500 GHz
ATM mode : VC-Mux
Header Compression : None
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS)
IDU Output Power : -18.3 dBm
ODU Output Power : 32.8 dBm
EIRP
                     : 52.0 dBW
Es/No
                     : 11.5 dB
Header Compression : Disabled
Timing correction : -132 us (256853 us)
Frequency correction: -260 Hz
System Information:
  Name : VIVO-PER-31238856--MG
  Location :Padre Carvalho
  Contact
  System Up time : 0 days, 03:40:11
  CPU Load : 18%
  System time(UTC) : 12 May 2017 15:46:03
  Broadcast Message : not set
HW:
         : SatLink 2000
: 120033
  Model
  HW ID
  Main board ID : 120026 R6.2
MAC addresses:
  Ethernet (LAN) : 00:20:0e:10:8E:13
  Satellite (DVB) : 00:20:0e:10:8E:13
Disparando 172.18.132.120 com 32 bytes de dados:
Resposta de 172.18.132.120 bytes=32 tempo=690ms TTL=62
Resposta de 172.18.132.120 bytes=32 tempo=1828ms TTL=62
```

