

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Ederson Martins Pires

GRE/Prodemge: João Antinossi Responsável/cliente: Sirleny Ramos Pestana

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-JOIS-23823 2Mbps





Satellite (DVB) RX Configuration ______ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0

Yes

8.883000 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.173571 GHz : 13.333014 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 14 8PSK-3/4 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.1 dB Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -18 dBm
Auto start
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
            : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.2 dBm
Es/No : 17.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -280 us (259448 us)
Frequency correction: 210 Hz
System Information:
    Name
                         : SEE-JOIS-23823
    Location
                         : JOSEN | POLIS / MG
    Contact
    System Up time : 0 days, 00:05:05
CPU Load : 20%
System time(UTC) : 30 January 2018 18:15:07
Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:94:e8 Satellite (DVB) : 00:20:0e:10:94:e8
   Ethernet (LAN)
NetAddr
             State MacAddr
                                          Ιf
10.213.217.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.217.1 with 32 bytes of data:
Reply from 10.213.217.1: bytes=32 time=986ms TTL=56
Reply from 10.213.217.1: bytes=32 time=528ms TTL=56
Reply from 10.213.217.1: bytes=32 time=531ms TTL=56
Reply from 10.213.217.1: bytes=32 time=522ms TTL=56
Reply from 10.213.217.1: bytes=32 time=585ms TTL=56
Reply from 10.213.217.1: bytes=32 time=539ms TTL=56
Reply from 10.213.217.1: bytes=32 time=565ms TTL=56
Reply from 10.213.217.1: bytes=32 time=555ms TTL=56
Reply from 10.213.217.1: bytes=32 time=536ms TTL=56
Reply from 10.213.217.1: bytes=32 time=527ms TTL=56
Ping statistics for 10.213.217.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 986ms, Average = 587ms
```

Lista de sites acessados:
www.globo.com _ ok
<u>www.globo.com</u> – ok <u>www.yahoo.com</u> – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável: Sirleny Ramos Pestana Função: Diretor MASP: 961.710-1
Telefone: 038 3736-9123