

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente Ivan Ribeiro

> Porta kbps Consórcio **VSAT-ID Plataforma** EMC/Vodanet **SEE-RIAS-22553** 2Mbps **VSAT**

> > Port eth 0 on SEE-RIAS-22553(10.213.136.1)



SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

12.176420 DVB-S2 104 * 0 0 4.883300 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet : 12.176216 GHz Network

Frequency Symbol Rate : 4.882940 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

Pilot : On

```
Frame length
                   : Short
                   : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                   : 14.2 dB
SNR
Input Power
                   : -37 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled : DU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -16.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Es/No
                   : 13.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -296 us (280550 us)
Frequency correction: 130 Hz
# arp show
                                           Ιf
                State MacAddr
   NetAddr
   10.213.136.2 Dynamic 80:ee:73:a4:e2:ba 1
# device show
System Information:
   Name
                      : SEE-RIAS-22553
    Location
                       : Rio Pardo de Minas - MG
    Contact
   System Up time : 0 days, 00:48:44
CPU Load : 7%
System time(UTC) : 11 November 2017 17:15:13
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:58:8b
    Satellite (DVB)
                       : 00:20:0e:10:58:8b
Pinging 10.213.136.1 with 32 bytes of data:
Reply from 10.213.136.1: bytes=32 time=563ms TTL=56
Reply from 10.213.136.1: bytes=32 time=580ms TTL=56
Reply from 10.213.136.1: bytes=32 time=516ms TTL=56
Reply from 10.213.136.1: bytes=32 time=557ms TTL=56
Reply from 10.213.136.1: bytes=32 time=577ms TTL=56
Reply from 10.213.136.1: bytes=32 time=577ms TTL=56
Reply from 10.213.136.1: bytes=32 time=528ms TTL=56
Reply from 10.213.136.1: bytes=32 time=587ms TTL=56
Reply from 10.213.136.1: bytes=32 time=551ms TTL=56
Reply from 10.213.136.1: bytes=32 time=550ms TTL=56
```

Ping statistics for 10.213.136.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 516ms, Maximum = 587ms, Average = 548ms Lista de sites acessados: www.globo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok Responsável pelo teste de navegação: Nome: Ivan Ribeiro Função: Secretario Identidade: 132098-7 Telefone: 038-9-9124-1342 Horario: 06:00 às 12:00