

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Vinicius Moreira

> Porta kbps Consórcio **VSAT-ID Plataforma SEE-FEOS-23781** EMC/Vodanet 2Mbps **VSAT**





dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 12.176420 DVB-S2 104 * 0 0 0 0.0 E

Yes

1 0 0.0 E 12.176420 DVB-S2 2 1 4.883300

Yes

Satellite (DVB) Receiver Status _____

Rx State

DVB State

Network

: On
: Forward link up
: 65281, Prodemge@Vodanet
: 12.176451 GHz
: 8.883010 ** Frequency : 8.883019 Msps Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short
DVB S2 Mode : ACM : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20

```
SNR
                   : 16.0 dB
                   : -38 dBm
Input Power
# dvb tx show
Satellite (DVB) TX Configuration
_____
                   : Enabled
Auto start
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                   : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.9 dBm
Es/No : 14.0 dB
Header Compression \,:\, Disabled \, - HC for RCS2 not supported by HUB
Timing correction : -358 us (266380 us)
Frequency correction: 130 Hz
# arp show
                State MacAddr
   NetAddr
                                          Τf
    10.215.73.2 Dynamic 64:1c:67:62:2e:12 1
# device show
System Information:
   Name
                      : SEE-FEOS-23781
    Location
                      : Ferros - MG
    Contact
   Broadcast Message : not set
HW:
    Model
                      : SatLink 2000
    HW ID
                      : 120033
    Main board ID
                      : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:94:f7
Satellite (DVB) : 00:20:0e:10:94:f7
Pinging 10.215.73.1 with 32 bytes of data:
Reply from 10.215.73.1: bytes=32 time=581ms TTL=56
Reply from 10.215.73.1: bytes=32 time=538ms TTL=56
Reply from 10.215.73.1: bytes=32 time=560ms TTL=56
Reply from 10.215.73.1: bytes=32 time=529ms TTL=56
Reply from 10.215.73.1: bytes=32 time=536ms TTL=56
Reply from 10.215.73.1: bytes=32 time=586ms TTL=56
Reply from 10.215.73.1: bytes=32 time=544ms TTL=56
Reply from 10.215.73.1: bytes=32 time=566ms TTL=56
Reply from 10.215.73.1: bytes=32 time=544ms TTL=56
Reply from 10.215.73.1: bytes=32 time=524ms TTL=56
Ping statistics for 10.215.73.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 524ms, Maximum = 586ms, Average = 551ms
```

Lista de sites acessados:		
<u>www.globo.com</u> – ok		
<u>www.yahoo.com</u> – ok		
<u>www.hotmail.com</u> – ok		
www.google.com – ok		
www.educacao.mg.gov.br – ok		
www.prodemge.gov.br – ok		
www.proderiige.gov.bi		
D		
Responsável pelo teste de navegação	:	
Nome:Rafael Vinicius Moreira		
Cargo: Secretário		
Masp:13577465-2		