


## **TERMO DE ACEITE TÉCNICO**

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Wallace Teixeira

Cliente: Vivo

Empresa
EMC Brasil
VIVO-PER-24060801-RN
256K/128K
VSAT



dvb tx show

## Satellite (DVB) TX Configuration

-----

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW

Default CW Frequency: 14.125750 GHz

ATM mode : VC-Mux Header Compression : None

## Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS2)

IDU Output Power : -16.0 dBm ODU Output Power : 33.0 dBm

: 46.3 dBW EIRP Es/No : 13.5 dB Header Compression : Disabled

Timing correction : -27 us (251236 us)

Frequency correction: -70 Hz

# dvb rx show

Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable \* 0 0 25.333333 12.050000 DVB-S2 102 0 0.0 E Yes 7 7 30.000000 12.050000 DVB-S2 102 0 0.0 E Yes

## Satellite (DVB) Receiver Status

\_\_\_\_\_

Rx State : On

DVB State : Forward link up
Network : 1326, T14R Beam
Frequency : 12.050139 GHz
Symbol Rate : 25.332944 Msps

S2 ModCod

- receiving : 12 8PSK-3/5 - current max : 22 16APSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.7 : 14.7 dB Input Power : -28 dBm

```
Resporta de 8.8.8.8: bytes=32 tenpo=763ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=846ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=555ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=7575ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=2835ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=2835ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=7575ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=573ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=766ms ITL-44
Resporta de 8.8.8.8: bytes=32 tenpo=578ms ITL-44
Resporta de 8.8.8.8: bytes=32 ten
```