


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Fabio Fernandes

GRE/Prodemge: João Antinossi Responsável/cliente : Itaceli Araujo

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-RIHO-220492MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 15/10/2017 15:01:22

## Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

## Satellite (DVB) Receiver Status

-----

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency: 12.176551 GHz Symbol Rate: 4.883029 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 16 8PSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

```
Roll off
            : 0.20
SNR
            : 16.1 dB
Input Power
               : -39 dBm
Satellite (DVB) TX Configuration
Auto start
              : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
            : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
State
            : On (DVB-RCS2)
IDU Output Power : -16.7 dBm
ODU Output Power : 33.0 dBm
EIRP
            : 46.3 dBW
Es/No
            : 13.0 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction: -346 us (281404 us)
Frequency correction: 120 Hz
#
 # arp show
 NetAddr
            State MacAddr
                                  If
  10.213.30.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.212.121.1 with 32 bytes of data:
Reply from 10.212.121.1: bytes=32 time=582ms TTL=56
Reply from 10.212.121.1: bytes=32 time=564ms TTL=56
Reply from 10.212.121.1: bytes=32 time=580ms TTL=56
Reply from 10.212.121.1: bytes=32 time=561ms TTL=56
Reply from 10.212.121.1: bytes=32 time=584ms TTL=56
Reply from 10.212.121.1: bytes=32 time=577ms TTL=56
Reply from 10.212.121.1: bytes=32 time=582ms TTL=56
Reply from 10.212.121.1: bytes=32 time=643ms TTL=56
Reply from 10.212.121.1: bytes=32 time=561ms TTL=56
Reply from 10.212.121.1: bytes=32 time=622ms TTL=56
Reply from 10.212.121.1: bytes=32 time=575ms TTL=56
Reply from 10.212.121.1: bytes=32 time=599ms TTL=56
Ping statistics for 10.212.121.1:
  Packets: Sent = 12, Received = 12, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
  Minimum = 561ms, Maximum = 643ms, Average = 585ms
```

Sites acessados www.globo.com ok www.yahoo.com.br- ok www.hotmail.com- ok www.google.com – ok www.prodemge.gov.br – ok Nome do responsável: Itaceli Araujo Telefone: 33-3436-1291 Cargo: Diretora MASP: 1081367-3