


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Cunha Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Soraya Jamel

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-TENI-22985 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 27/11/2017 23:54:49

dvb rx show

Satellite (DVB) RX Configuration ______ : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 0 0.0 E 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176386 GHz : 4.883096 Msps Frequency Symbol Rate : 4.883096 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot Pilot Frame length : On : Short DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 15.3 dB
SNR
Input Power
                    : -30 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.1 dBm
ODU Output Power : 33.8 dBm
EIRP
                     : 47.1 dBW
EIRP
Es/No
                     : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -101 us (280530 us)
Frequency correction: 80 Hz
# device show
System Information:
    Name
                        : SEE-TENI-22985
    Location
                         : TE FILO OTONI - MG
    Contact
                        :
    System Up time : 0 days, 02:42:55
CPU Load : 24%
System time(UTC) : 27 November 2017 23:08:59
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:55:33
Satellite (DVB) : 00:20:0e:10:55:33
# arp show
   NetAddr
                 State MacAddr
   10.215.185.2 Dynamic b8:70:f4:6e:b3:ab 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -n 15 10.215.185.1
Pinging 10.215.185.1 with 32 bytes of data:
Reply from 10.215.185.1: bytes=32 time=686ms TTL=56
Reply from 10.215.185.1: bytes=32 time=562ms TTL=56
Reply from 10.215.185.1: bytes=32 time=597ms TTL=56
Reply from 10.215.185.1: bytes=32 time=568ms TTL=56
Reply from 10.215.185.1: bytes=32 time=570ms TTL=56
Reply from 10.215.185.1: bytes=32 time=557ms TTL=56
Reply from 10.215.185.1: bytes=32 time=557ms TTL=56
Reply from 10.215.185.1: bytes=32 time=555ms TTL=56
Reply from 10.215.185.1: bytes=32 time=535ms TTL=56
```

```
Reply from 10.215.185.1: bytes=32 time=578ms TTL=56
Reply from 10.215.185.1: bytes=32 time=553ms TTL=56
Reply from 10.215.185.1: bytes=32 time=551ms TTL=56
Reply from 10.215.185.1: bytes=32 time=524ms TTL=56
Reply from 10.215.185.1: bytes=32 time=575ms TTL=56
Reply from 10.215.185.1: bytes=32 time=575ms TTL=56
Reply from 10.215.185.1: bytes=32 time=553ms TTL=56

Ping statistics for 10.215.185.1:
    Packets: Sent = 15, Received = 15, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 524ms, Maximum = 686ms, Average = 568ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

nome do responvavel : lineu euclecio alves cassemiro

telefone: (33) 35283014

cargo: diretor MASP: 958635-5 tecnico: Eduardo Tadra telefone: (11) 9 98331162