

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

Responsável/cliente: Osvaldo Jose dos Santos GRE/Prodemge: João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-RIAS-22566 2Mbps





Satellite (DVB) RX Configuration _____

: Enabled

Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176325 GHz : 4.883078 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.4 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -19.1 dBm
ODU Output Power : 32.7 dBm
EIRP
                    : 46.0 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -289 us (280656 us)
Frequency correction: 150 Hz
System Information:
    Name
                        : SEE-RIAS-22566
    Location
                        : Rio Pardo de Minas - MG
    Contact
    System Up time : 0 days, 00:51:39 CPU Load : 17%
    System time(UTC) : 09 November 2017 17:49:54
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:52:d9
Satellite (DVB) : 00:20:0e:10:52:d9
    Ethernet (LAN)
NetAddr
            State MacAddr
   10.213.149.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.213.149.1 with 32 bytes of data:
Reply from 10.213.149.1: bytes=32 time=543ms TTL=56
Reply from 10.213.149.1: bytes=32 time=722ms TTL=56
Reply from 10.213.149.1: bytes=32 time=531ms TTL=56
Reply from 10.213.149.1: bytes=32 time=567ms TTL=56
Reply from 10.213.149.1: bytes=32 time=536ms TTL=56
Reply from 10.213.149.1: bytes=32 time=531ms TTL=56
Reply from 10.213.149.1: bytes=32 time=539ms TTL=56
Reply from 10.213.149.1: bytes=32 time=555ms TTL=56
Reply from 10.213.149.1: bytes=32 time=548ms TTL=56
Reply from 10.213.149.1: bytes=32 time=533ms TTL=56
Ping statistics for 10.213.149.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 531ms, Maximum = 722ms, Average = 560ms
```

Lista de sites acessados:

<u>www.globo.com</u> – ok www.yahoo.com - ok

<u>www.hotmail.com</u> – ok

<u>www.google.com</u> – ok

<u>www.educacao.mg.gov.br</u> – ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Osvaldo Jose dos Santos

Função: ATB Financeiro

MASP: 12828711

Telefone: 38-99301390

Funcionamento: 07:00 às 11:20h