


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Fábio Francisco Oliveira

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-MASO-22178 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.176436 GHz Symbol Rate : 4.882944 Msps

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.3 dB SNR Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
-----
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -21.2 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Es/No
                     : 13.0 dB
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -173 us (280910 us)
Frequency correction: 90 Hz
System Information:
   Name
                        : SEE-MASO-22178
    Location
                        : MATIAS CARDOSO - MG
    Contact
    System Up time : 0 days, 00:07:19 CPU Load : 9%
    System time(UTC) : 26 October 2017 21:58:14 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5d:63
Satellite (DVB) : 00:20:0e:10:5d:63
# arp show
   NetAddr
              State MacAddr
   10.212.231.2 Dynamic 74:e6:e2:d4:e4:73 1
C:\ >ping -t 10.212.231.1
Pinging 10.212.231.1 with 32 bytes of data:
Reply from 10.212.231.1: bytes=32 time=584ms TTL=56
Reply from 10.212.231.1: bytes=32 time=580ms TTL=56
Reply from 10.212.231.1: bytes=32 time=546ms TTL=56
Reply from 10.212.231.1: bytes=32 time=563ms TTL=56
Reply from 10.212.231.1: bytes=32 time=608ms TTL=56
Reply from 10.212.231.1: bytes=32 time=572ms TTL=56
Reply from 10.212.231.1: bytes=32 time=569ms TTL=56
Reply from 10.212.231.1: bytes=32 time=571ms TTL=56
Reply from 10.212.231.1: bytes=32 time=575ms TTL=56
```

```
Reply from 10.212.231.1: bytes=32 time=584ms TTL=56

Ping statistics for 10.212.231.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 546ms, Maximum = 608ms, Average = 575ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação:

Nome: Fábio Francisco Oliveira

Telefone:38-998224515

Função: Diretor Masp: 127380011

Funcionamento: 13:00 às 22:30h