


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Ederson Martins Pires

**GRE/Prodemge:** João Antinossi Responsável/cliente: Vera Lúcia Camargos

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-MIAS-21927 2Mbps



Configuration Saved

Satellite (DVB) RX Configuration \_\_\_\_\_\_ : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

Satellite (DVB) Receiver Status

DVB State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176310 GHz

Symbol Rate : 4.883032 March | S2 ModCod

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 17.2 dB : -30 dBm Input Power

```
Satellite (DVB) TX Configuration
 ______
Auto start
                                            : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                                            : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.3 dBm

ODU Output Power : 33.3 dBm

EIRP
______
Es/No
                                             : 16.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -357 us (280903 us)
Frequency correction: -20 Hz
System Information:
        Name
                                                    : SEE-MIAS-21927
         Location
                                                     : Minas Novas - MG
         Contact
        System Up time : 0 days, 00:35:09 CPU Load : 10%
         System time (UTC) : 11 October 2017 11:57:40
         Broadcast Message : not set
HW:
         Model
                                                    : SatLink 2000
                                                    : 120033
         HW ID
         Main board ID
                                                    : 120026 R6.2
         | : 00:20:0e:10:4f:2d 
MAC addresses:
        Ethernet (LAN)
Pinging 10.212.15.1 with 32 bytes of data:
Reply from 10.212.15.1: bytes=32 time=536ms TTL=56
Reply from 10.212.15.1: bytes=32 time=556ms TTL=56
Reply from 10.212.15.1: bytes=32 time=579ms TTL=56
Reply from 10.212.15.1: bytes=32 time=544ms TTL=56
Reply from 10.212.15.1: bytes=32 time=593ms TTL=56
Reply from 10.212.15.1: bytes=32 time=538ms TTL=56
Reply from 10.212.15.1: bytes=32 time=572ms TTL=56
Reply from 10.212.15.1: bytes=32 time=631ms TTL=56
Reply from 10.212.15.1: bytes=32 time=550ms TTL=56
Reply from 10.212.15.1: bytes=32 time=855ms TTL=56
Ping statistics for 10.212.15.1:
         Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
         Minimum = 536ms, Maximum = 855ms, Average = 595ms
```

Lista de sites acessados:
www.globo.com – ok www.hotmail.com – ok www.google.com – ok www.educacao.mg.gov.br – ok
Responsável pelo teste de navegação: Nome: Vera Lúcia Camargos Função: Diretora Identidade: 12 121 5554 Telefone: (33) 3765-2945