


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Fabio Fernandes

**GRE/Prodemge:** João Antinossi Responsável/cliente: Aparecida Alves Pereira

> Consórcio **VSAT-ID** Porta kbps EMC/Vodanet SEE-SAUI-22389 2Mbps **VSAT**



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

: Forward link up DVB State

Network

: 65281, Prodemge@Vodanet : 12.176368 GHz : 4.882955 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.9 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -25 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-I
IDU Output Power : -14.3 dBm
ODU Output Power : 32.1 dBm
                    : On (DVB-RCS2)
State
EIRP
                    : 45.4 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -236 us (281138 us)
Frequency correction: 200 Hz
System Information:
                   : SEE-SAUI-22389
   Name
    Location
                        : SANTA MARIA DO SUAÇUÍ - MG
    Contact
   System Up time : 0 days, 00:19:53
CPU Load : 15%
    System time(UTC) : 26 October 2017 17:48:10
    Broadcast Message : not set
HW:
                       : SatLink 2000
    Model
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5b:16
Satellite (DVB) : 00:20:0e:10:5b:16
NetAddr
            State MacAddr
     10.215.5.2 Dynamic 00:23:5a:6b:ac:b8 1
Pinging 10.215.5.1 with 32 bytes of data:
Reply from 10.215.5.1: bytes=32 time=545ms TTL=56
Reply from 10.215.5.1: bytes=32 time=587ms TTL=56
Reply from 10.215.5.1: bytes=32 time=541ms TTL=56
Reply from 10.215.5.1: bytes=32 time=563ms TTL=56
Reply from 10.215.5.1: bytes=32 time=561ms TTL=56
Reply from 10.215.5.1: bytes=32 time=561ms TTL=56
Reply from 10.215.5.1: bytes=32 time=549ms TTL=56
Reply from 10.215.5.1: bytes=32 time=546ms TTL=56
Reply from 10.215.5.1: bytes=32 time=547ms TTL=56
Reply from 10.215.5.1: bytes=32 time=553ms TTL=56
Ping statistics for 10.215.5.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 541ms, Maximum = 587ms, Average = 555ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
www.prodemge.gov.br – ok
<u>www.prodernge.gov.br</u> ok
Danage (
Responsável pelo teste de navegação:
Nome: Aparecida Alves Pereira
Função: Vice-Diretora
Identidade: MASP 992082-8
Telefone:
Horário de funcionamento – 07:00 as 17:00
Tiorario de funcionamento – 07.00 as 17.00