


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Joao Gustavo

**GRE/Prodemge:** João Antinossi Responsável/cliente: José Heleno Cardoso de Sá

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-MOUL-22539 2Mbps **VSAT**



Satellite (DVB) RX Configuration \_\_\_\_\_ : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 \* 0 0 0 0.0 E

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.175921 GHz Frequency Symbol Rate : 4.882862 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 16APSK-5/6 - current max : 21

Pilot : On Frame length : Shor : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB : -29 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                     : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.9 dBm
ODU Output Power : 35.5 dBm
EIRP
                     : 48.8 dBW
Es/No
                     : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -263 us (280807 us)
Frequency correction: 160 Hz
System Information:
                    : SEE-MOUL-22539
    Name
    Location
                         : Monte Azul - MG
    Contact
    System Up time : 0 days, 00:26:16
CPU Load : 16%
System time(UTC) : 08 November 2017 18:48:50
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5c:93
Satellite (DVB) : 00:20:0e:10:5c:93
NetAddr
             State MacAddr
   10.213.122.2 Dynamic b4:99:ba:00:92:6b
Pinging 10.213.122.1 with 32 bytes of data:
Reply from 10.213.122.1: bytes=32 time=623ms TTL=56
Reply from 10.213.122.1: bytes=32 time=520ms TTL=56
Reply from 10.213.122.1: bytes=32 time=596ms TTL=56
Reply from 10.213.122.1: bytes=32 time=528ms TTL=56
Reply from 10.213.122.1: bytes=32 time=543ms TTL=56
Reply from 10.213.122.1: bytes=32 time=551ms TTL=56
Reply from 10.213.122.1: bytes=32 time=561ms TTL=56
Reply from 10.213.122.1: bytes=32 time=540ms TTL=56
Reply from 10.213.122.1: bytes=32 time=530ms TTL=56
Reply from 10.213.122.1: bytes=32 time=535ms TTL=56
Ping statistics for 10.213.122.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 520ms, Maximum = 623ms, Average = 552ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: José Heleno Cardoso de Sá
Função: Diretor
MASP: 859749-4
Telefone: 38-99839-8126
Telefolic. 38-99639-6120
Funcionamento: 07:00 às 17:20h
Funcionamento. 07.00 as 17.20n