


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Robson Nikitin

GRE/Prodemge: João Antinossi Responsável/cliente: Meiry Rose S. Lopes Souza

> Consórcio VSAT-ID Porta kbps Plataforma EMC/Vodanet SEE-SAES-22237 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 3/11/2017 15:09:09

Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdoq : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176497 GHz Symbol Rate : 4.883069 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.8 dB Input Power : -29 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -19.2 dBm

ODU Output Power : 33.2 dBm

EIRP
_____
Es/No
                    : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -438 us (281149 us)
Frequency correction: 70 Hz
System Information:
    Name
                        : SEE-SACO-22221
    Location
                        : S¦O FRANCISCO
    Contact
    System Up time : 0 days, 00:25:12 CPU Load : 12%
    System time (UTC) : 03 November 2017 12:03:17
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:48:93
Satellite (DVB) : 00:20:0e:10:48:93
    Ethernet (LAN)
Reply from 10.213.36.1: bytes=32 time=541ms TTL=56
Reply from 10.213.36.1: bytes=32 time=549ms TTL=56
Reply from 10.213.36.1: bytes=32 time=554ms TTL=56
Reply from 10.213.36.1: bytes=32 time=562ms TTL=56
Reply from 10.213.36.1: bytes=32 time=550ms TTL=56
Reply from 10.213.36.1: bytes=32 time=546ms TTL=56
Reply from 10.213.36.1: bytes=32 time=547ms TTL=56
Reply from 10.213.36.1: bytes=32 time=556ms TTL=56
Reply from 10.213.36.1: bytes=32 time=553ms TTL=56
Reply from 10.213.36.1: bytes=32 time=587ms TTL=56
Ping statistics for 10.213.36.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 541ms, Maximum = 587ms, Average = 554ms
NetAddr
           State
                     MacAddr
    10.213.36.2 Dynamic 70:5a:b6:eb:69:8a 1
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
<u>www.proderinge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Meiry Rose S. Lopes Souza
Função: Diretora
Telefone: 38-99893-5129
MASP: 1000195-6
Horário 08:00 às 22:30