

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior


GRE/Prodemge: João Antinossi

Consórcio
EMC/Vodanet

Porta kbps
SEE-BURE-23137

Porta kbps
VSAT





dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176411 GHz Symbol Rate : 4.883025 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.4 dB Input Power : -34 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -22.6 dBm
ODU Output Power : 33.0 dBm

EIRP : 46.3 dBW Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -283 us (281372 us)

Frequency correction: 150 Hz

arp show

NetAddr State MacAddr If 10.214.122.2 Dynamic 64:1c:67:61:83:29 1

device show

System Information:

Name : SEE-BURE-23137 Location : BUGRE - MG

Contact

System Up time : 0 days, 00:10:38

CPU Load : 15%

System time(UTC) : 07 December 2017 17:22:10

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:58:d3 Satellite (DVB) : 00:20:0e:10:58:d3

#

Pinging 10.214.122.1 with 32 bytes of data:

```
Reply from 10.214.122.1: bytes=32 time=571ms TTL=56 Reply from 10.214.122.1: bytes=32 time=530ms TTL=56 Reply from 10.214.122.1: bytes=32 time=577ms TTL=56 Reply from 10.214.122.1: bytes=32 time=555ms TTL=56 Reply from 10.214.122.1: bytes=32 time=614ms TTL=56 Reply from 10.214.122.1: bytes=32 time=533ms TTL=56 Reply from 10.214.122.1: bytes=32 time=530ms TTL=56 Reply from 10.214.122.1: bytes=32 time=731ms TTL=56 Reply from 10.214.122.1: bytes=32 time=688ms TTL=56 Reply from 10.214.122.1: bytes=32 time=688ms TTL=56 Reply from 10.214.122.1: bytes=32 time=565ms TTL=56
```

Ping statistics for 10.214.122.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 530ms, Maximum = 731ms, Average = 589ms

Resp: Maria Geralda Leal de Sousa

Cargo: Diretora Masp:277485-9

Telefone:031-9-9278-1950

Horario:07:00-16:15 Onde ficou: Secretaria www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com