

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Elida Cristine Costa

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet SEE-BELO-22760 2Mbps VSAT





Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E 4.883300 * 0 0

Yes

11.962753 DVB-S2 2 0 0.0 E 16.667000 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prodei : 12.176273 GHz Frequency Symbol Rate : 4.883055 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.4 dB SNR Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.5 dBm
ODU Output Power : 33.0 dBm
EIRP
                   : 46.3 dBW
Es/No
                   : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -272 us (280888 us)
Frequency correction: 120 Hz
System Information:
   Name
                       : SEE-BELO-22760
    Location
                       : Berilo - MG
    Contact
   System Up time : 0 days, 00:41:13 CPU Load : 15%
   System time (UTC) : 13 November 2017 17:46:18
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
   MAC addresses:
NetAddr
            State MacAddr
    10.214.66.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.214.66.1 with 32 bytes of data:
Reply from 10.214.66.1: bytes=32 time=681ms TTL=56
Reply from 10.214.66.1: bytes=32 time=607ms TTL=56
Reply from 10.214.66.1: bytes=32 time=579ms TTL=56
Reply from 10.214.66.1: bytes=32 time=550ms TTL=56
Reply from 10.214.66.1: bytes=32 time=570ms TTL=56
Reply from 10.214.66.1: bytes=32 time=571ms TTL=56
Reply from 10.214.66.1: bytes=32 time=627ms TTL=56
Reply from 10.214.66.1: bytes=32 time=549ms TTL=56
Reply from 10.214.66.1: bytes=32 time=604ms TTL=56
Reply from 10.214.66.1: bytes=32 time=516ms TTL=56
Ping statistics for 10.214.66.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 516ms, Maximum = 681ms, Average = 585ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Mary dos Santos Pereira
Função: Diretora
MASP: 636469-9
Telefone: 33-3512-1131
Francis and a 07,00 \cdot 22,001
Funcionamento: 07:00 às 22:00h