


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Cunha Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Soraya Jamel

> Consórcio **VSAT-ID** Porta kbps **Plataforma** 2048/1024 EMC/Vodanet SEE-ITRI-22820 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 12/11/2017 00:57:54

dvb rx show

Satellite (DVB) RX Configuration _____ : Enabled Auto start

Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

0 0.0 E

Enable

4.883300 12.176420 DVB-S2 104 0 * 0 0 0.0 E Yes

11.962753 DVB-S2 2

1 Yes

Satellite (DVB) Receiver Status

16.667000

Rx State

DVB State

: On: Forward link up: 65281, Prodemge@Vodanet

. 05281, Prode:
12.176450 GHz
Symbol Rate : 4.883005

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                    : 16.0 dB
Input Power
                    : -33 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -16.7 dBm
ODU Output Power : 32.9 dBm
EIRP
                    : 46.2 dBW
Es/No
                     : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -94 us (280901 us)
Frequency correction: 60 Hz
# device show
System Information:
              : SEE-ITRI-22820
    Name
                        : Itambacuri - MG
    Location
    Contact
                        :
    System Up time : 0 days, 01:46:54
CPU Load : 27%
System time(UTC) : 12 November 2017 00:16:19
    Broadcast Message : not set
HW:
                        : SatLink 2000
    Model
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:69:8f
Satellite (DVB) : 00:20:0e:10:69:8f
# arp show
                State MacAddr
   10.215.114.2 Dynamic b8:70:f4:6e:b3:ab 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -n 10 10.215.114.1
Pinging 10.215.114.1 with 32 bytes of data:
Reply from 10.215.114.1: bytes=32 time=578ms TTL=56
Reply from 10.215.114.1: bytes=32 time=575ms TTL=56
Reply from 10.215.114.1: bytes=32 time=570ms TTL=56
Reply from 10.215.114.1: bytes=32 time=566ms TTL=56
Reply from 10.215.114.1: bytes=32 time=643ms TTL=56
Reply from 10.215.114.1: bytes=32 time=576ms TTL=56
Reply from 10.215.114.1: bytes=32 time=593ms TTL=56
Reply from 10.215.114.1: bytes=32 time=554ms TTL=56
Reply from 10.215.114.1: bytes=32 time=581ms TTL=56
Reply from 10.215.114.1: bytes=32 time=693ms TTL=56
```

```
Ping statistics for 10.215.114.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 554ms, Maximum = 693ms, Average = 592ms
```

Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok

nome do responvavel : maria janete sousa passos

telefone: (33) 35115048

cargo: diretora MASP: 1289080-2 tecnico: Eduardo Tadra telefone: (11) 9 98331162