


TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

Cliente: VIVO NOC/Operador: Renan Borges Sousa

> **Empresa** VSAT-ID Link kbps Plataforma EMC Brasil VIVO-PER-31228699-MG 256/128 **VSAT**



Satellite (DVB) RX Configuration

Auto start : Enabled

Max MODCOD : 23 16APSK-9/10 (SNR threshold: 23.5 dB)

PV watchdox : 15 minute

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId Enable * 0 0 9.320000 12.055825 DVB-S2 4 Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 1326, GlobalIP@Telstar-14R

Symbol Rate : 9 310070
Symbol Rate : 9 310070

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 23 16APSK-9/10

Pilot : On Frame length : Short DVB S2 Mode : ACM Roll off : 0.25 SNR : 13.4 dB Input Power : -26 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
                   : max
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : None
Satellite (DVB) Transmitter Status
_____
State : On (TDMA)

IDU Output Power : -14.5 dBm

ODU Output Power : 35.3 dBm
EIRP
                   : 48.6 dBW
Eb/No
                   : 13.5 dB
Header Compression : Disabled
Timing correction : -240 us (260571 us)
Frequency correction: -320 Hz
# System Information:
IP DVB 10.50.0.19/32
#ping 8.8.8.8
# Request timed out
64 bytes from 8.8.8.8: time=540 ms
64 bytes from 8.8.8.8: time=560 ms
64 bytes from 8.8.8.8: time=730 ms
64 bytes from 8.8.8.8: time=1260 ms
--- 8.8.8.8 ping statistics ---
5 packets transmitted, 4 received, 20.00 percent packet loss
rtt min/avg/max = 540/770/1260 ms
```