


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Welington Pereira de jesus

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet SEE-CAUL-22991 2MBPS **VSAT**



# dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State

: Forward link up
: 65281, Prodemge@Vodanet Network

Frequency : 12.176555 GHz

Symbol Rate : 4.882990 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 17.0 dB
SNR
Input Power
                    : -38 dBm
# # dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.8 dBm
ODU Output Power : 33.0 dBm
EIRP
EIRP
                    : 46.3 dBW
                    : 10.5 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -289 us (281773 us)
Frequency correction: -170 Hz
# device show
System Information:
   Name
                        : SEE-CAUL-22991
    Location
                        : Campo Azul - MG
    Contact
                        :
    System Up time : 0 days, 00:02:46
CPU Load : 6%
System time(UTC) : 01 December 2017 05:41:47
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5e:93
Satellite (DVB) : 00:20:0e:10:5e:93
# arp show
   NetAddr State MacAddr
                                              Ιf
Pinging 10.215.199.1 with 32 bytes of data:
Reply from 10.215.199.1: bytes=32 time=542ms TTL=56
Reply from 10.215.199.1: bytes=32 time=553ms TTL=56
Reply from 10.215.199.1: bytes=32 time=558ms TTL=56
Reply from 10.215.199.1: bytes=32 time=555ms TTL=56
Reply from 10.215.199.1: bytes=32 time=539ms TTL=56
Reply from 10.215.199.1: bytes=32 time=585ms TTL=56
Reply from 10.215.199.1: bytes=32 time=554ms TTL=56
Reply from 10.215.199.1: bytes=32 time=583ms TTL=56
Reply from 10.215.199.1: bytes=32 time=546ms TTL=56
Reply from 10.215.199.1: bytes=32 time=590ms TTL=56
Ping statistics for 10.215.199.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
```

Approximate round trip times in milli-seconds:
Minimum = 539ms, Maximum = 590ms, Average = 560ms
Lista de sites acessados:
www.globo.com – ok
<u>www.yahoo.com</u> – ok <u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
www.prodeinge.gov.br
Responsável pelo teste de navegação:
Nome: Welington Pereira de jesus
Função: diretor
Identidade: Masp: 9319419