


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Walter Leandro

GRE/Prodemge: João Antinossi Responsável/cliente: José Francisco de Assis Reis

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-MUUM-23394 2Mbps **VSAT**



Satellite (DVB) RX Configuration

\_\_\_\_\_\_ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.173500 DVB-S2 104 \* 0 0 13.333333 0.0 E Yes

4.883300 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

12.173500 DVB-S2 104 0 0.0 E 9 9 13.333333

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 12.173329 GHz Frequency Symbol Rate : 13.333145 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 16APSK-5/6 - current max : 21

: On Pilot : Short : ACM Frame length DVB S2 Mode DVB S2 Stream type : MPEG-TS : 0.20 Roll off SNR : 14.1 dB Input Power : -27 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -18.3 dBm
ODU Output Power : 32.9 dBm
EIRP : 46.2 dBW
Es/No
                    : 13.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -217 us (259750 us)
Frequency correction: 60 Hz
System Information:
   Name
                        : SEE-MUUM-23394
    Location
                        : MUTUM - MG
    Contact
    System Up time : 0 days, 01:53:38 CPU Load : 30%
    System time(UTC) : 18 July 2018 17:12:40 Broadcast Message : not set
HW:
                        : SatLink 2000
    Model
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:57:41
    Satellite (DVB)
                       : 00:20:0e:10:57:41
NetAddr
            State MacAddr
    10.215.47.2 Dynamic e8:9a:8f:b7:bd:4a 1
C:\Windows\System32>ping 10.215.47.1 -n 10
Disparando 10.215.47.1 com 32 bytes de dados:
Resposta de 10.215.47.1: bytes=32 tempo=572ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=555ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=564ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=558ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=550ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=544ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=547ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=540ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=543ms TTL=57
Resposta de 10.215.47.1: bytes=32 tempo=563ms TTL=57
Estatísticas do Ping para 10.215.47.1:
    Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
             perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 540ms, Máximo = 572ms, Média = 553ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com - ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável: José Francisco de Assis Reis
Função: ATB
MASP: 1249644-4
Telefone: 33 3312-3168