


TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente Ronny Marcos Leal

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-MENA-229112MbpsVSAT





dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled

IDU Output Power : -20 dBm

IDU Max Output Power: 0.0 dBm

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux

Header Compression: UDP/IP

State : On (DVB-RCS2)

IDU Output Power : -19.9 dBm

Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -225 us (280398 us)

Frequency correction: 200 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency: 12.176457 GHz

Symbol Rate : 4.882978 Msps

S2 ModCod

- receiving : 15 8PSK-5/6

- current max : 21 16APSK-5/6

Pilot : On

Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20

SNR : 15.5 dB

Input Power : -40 dBm

arp show

NetAddr State MacAddr If

10.214.96.2 Dynamic b4:99:ba:00:92:6b 1

device show

System Information:

Name : SEE-MENA-22911

Location : MEDINA - MG

Contact :

System Up time : 0 days, 00:28:26

CPU Load : 15%

System time(UTC) : 27 November 2017 18:09:16

Broadcast Message : not set

HW:

Model : SatLink 2000

HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:56:31

Satellite (DVB) : 00:20:0e:10:56:31

Pinging 10.214.96.1 with 32 bytes of data:

Reply from 10.214.96.1: bytes=32 time=825ms TTL=56

Reply from 10.214.96.1: bytes=32 time=523ms TTL=56

Reply from 10.214.96.1: bytes=32 time=525ms TTL=56

Reply from 10.214.96.1: bytes=32 time=516ms TTL=56

Reply from 10.214.96.1: bytes=32 time=545ms TTL=56

Reply from 10.214.96.1: bytes=32 time=524ms TTL=56

Reply from 10.214.96.1: bytes=32 time=553ms TTL=56

Reply from 10.214.96.1: bytes=32 time=615ms TTL=56

Reply from 10.214.96.1: bytes=32 time=536ms TTL=56

Reply from 10.214.96.1: bytes=32 time=532ms TTL=56

Ping statistics for 10.214.96.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 516ms, Maximum = 825ms, Average = 569ms

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com

www.yahoo.com.br

Responsável: Ronny Marcos Leal

Cargo: Diretor

Telefone: 033-9-8819-9285

Funcionamento: 07:00-18:00

Onde ficou: Em um computador da diretoria.