

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Renata Lucia de Oliveira Campos

> Plataforma Consórcio **VSAT-ID** Porta kbps **VSAT** EMC/Vodanet SEE-DUDE-23656 2Mbps





Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

4.883300 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65261, ... : 12.176415 GHz : 8.883047 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.5 dB Input Power : -40 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -17 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -17.2 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -222 us (266192 us)
Frequency correction: 120 Hz
System Information:
                    : SEE-DUDE-23656
    Name
    Location
                         : Durande - MG
    Contact
    System Up time : 0 days, 00:24:14
CPU Load : 14%
System time(UTC) : 12 January 2018 19:17:20
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                        : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:7b:4c
Satellite (DVB) : 00:20:0e:10:7b:4c
NetAddr State MacAddr
    10.215.15.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.215.15.1 with 32 bytes of data:
Reply from 10.215.15.1: bytes=32 time=530ms TTL=56
Reply from 10.215.15.1: bytes=32 time=527ms TTL=56
Reply from 10.215.15.1: bytes=32 time=605ms TTL=56
Reply from 10.215.15.1: bytes=32 time=556ms TTL=56
Reply from 10.215.15.1: bytes=32 time=578ms TTL=56
Reply from 10.215.15.1: bytes=32 time=540ms TTL=56
Reply from 10.215.15.1: bytes=32 time=565ms TTL=56
Reply from 10.215.15.1: bytes=32 time=543ms TTL=56
Reply from 10.215.15.1: bytes=32 time=567ms TTL=56
Reply from 10.215.15.1: bytes=32 time=553ms TTL=56
Ping statistics for 10.215.15.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 527ms, Maximum = 605ms, Average = 556ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com – ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Renata Lucia de Oliveira Campos Função: Diretora MASP: 812459-6 Telefone: 33-3342-1210 Horário: 07:00 as 22:00