

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: JEAN POLINI

Responsável/cliente: CILEIA DOMINGOS S. FERREIRA GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma EMC/Vodanet** SEE-CONA-23183 2Mbps **VSAT**

Port eth0 on SEE-CONA-23183 (10.214.203.1)



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network: 65281, Prodemge@Vodanet

Frequency: 12.176354 GHz Symbol Rate: 8.883087 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 19 16APSK-3/4

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 12.8 dB

Input Power: -41 dBm

```
# dvb tx show
Satellite (DVB) TX Configuration
Auto start : Enabled
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power: 33.2 dBm
EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -4.2 dBm
ODU Output Power : 33.6 dBm
EIRP : 46.9 dBW
Es/No : 15.0 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction: -147 us (265845 us)
Frequency correction: -100 Hz
# device show
System Information:
Name: SEE-CONA-23183
Location : Conselheiro Pena - MG
Contact :
System Up time : 0 days, 05:42:54
CPU Load : 6%
System time(UTC) : 11 December 2017 03:38:39
Broadcast Message : not set
HW:
Model : SatLink 2000
HW ID : 120033
Main board ID : 120026 R6.2
MAC addresses:
Ethernet (LAN) : 00:20:0e:10:4a:f0
Satellite (DVB) : 00:20:0e:10:4a:f0
# arp show
NetAddr State MacAddr If
#
Pinging 10.214.203.1 with 32 bytes of data:
Reply from 10.214.203.1: bytes=32 time=598ms TTL=56
Reply from 10.214.203.1: bytes=32 time=572ms TTL=56
Reply from 10.214.203.1: bytes=32 time=533ms TTL=56
Reply from 10.214.203.1: bytes=32 time=532ms TTL=56
Reply from 10.214.203.1: bytes=32 time=529ms TTL=56
Reply from 10.214.203.1: bytes=32 time=548ms TTL=56
Reply from 10.214.203.1: bytes=32 time=552ms TTL=56
Reply from 10.214.203.1: bytes=32 time=529ms TTL=56
Reply from 10.214.203.1: bytes=32 time=566ms TTL=56
Reply from 10.214.203.1: bytes=32 time=557ms TTL=56
Ping statistics for 10.214.203.1:
Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
Minimum = 529ms, Maximum = 598ms, Average = 551ms
```

Lista de sites acessados: www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok
Responsável pelo teste de navegação: Nome: CILEIA DOMINGOS S. FERREIRA Função: DIRETORA Identidade: MASP:391387-8